

# REHABILITATION ASSESSMENT REPORT

## New Creek Watershed Site 17

Mineral County, West Virginia



**Project Sponsors:** Potomac Valley Conservation District  
City of Keyser, WV  
West Virginia State Conservation Committee

**National Inventory of Dams (NID) ID: WV 05706**

**Total Failure Index: 273**

**Population at Risk: 1143**

**Total Risk Index: 12482**

**Hazard Classification: High**

**March 2011**

REHABILITATION ASSESSMENT REPORT

**NEW CREEK WATERSHED SITE 17**

Mineral County, West Virginia

National Inventory of Dams (NID) ID: WV 05706

Project Sponsors:

POTOMAC VALLEY CONSERVATION DISTRICT  
CITY OF KEYSER, WV  
WEST VIRGINIA STATE CONSERVATION COMMITTEE

March 2011

Prepared for

WEST VIRGINIA NRCS  
MORGANTOWN, WEST VIRGINIA

Prepared by

GANNETT FLEMING, INC.  
HARRISBURG PENNSYLVANIA



## **REHABILITATION ASSESSMENT REPORT**

### **New Creek Watershed Site 17**

Mineral County, West Virginia

### **Table of Contents**

	<b><u>Page</u></b>
1. Introduction and Purpose .....	1
2. Project Setting and History .....	1
3. Site Inspection Summary and Operation and Maintenance .....	2
4. Hydrologic and Hydraulic Analyses .....	6
5. Spillway Integrity Analyses .....	7
6. Breach Inundation Mapping and Hazard Classification Summary .....	9
7. Review of Available Geotechnical Information .....	12
8. Failure and Risk Indexes .....	13
9. Discussion of Potential Rehabilitation Alternatives .....	13
10. Cost Estimates for Rehabilitation Alternatives .....	13
11. Conclusions and Recommendations .....	15

### **Exhibits**

Exhibit 1	Project Map for the New Creek Watershed	
Exhibit 2	Limits of the Maximum Pool Elevation and the Downstream Inundation Limits on Orthophoto Base Map	
Exhibit 3	Limits of the Maximum Pool Elevation and the Downstream Inundation Limits on USGS 7.5 Minute Quadrangle Base Map	

### **Appendices**

Appendix A	Selected As-Built Drawings	
Appendix B	Site Inspection Checklist and Photographs	
Appendix C	SITES Output	
Appendix D	Evaluation of Potential Rehabilitation Projects-Priority Ranking Spreadsheet	



## **1. Introduction and Purpose**

The purpose of this report is to provide the West Virginia Natural Resources Conservation Service (NRCS) an assessment of New Creek Site 17, as authorized by contract dated May 24, 2010 for 41 Dam Assessments for various watersheds in West Virginia (Award No. AG-3D47-D-10-0008). The report provides a description of the dam, an assessment of the current conditions and status of operation and maintenance, and the scope of potential rehabilitation alternatives. In addition to assessing the overall integrity of the structure, available design information was reviewed to determine whether the structure meets current NRCS design criteria. This information is provided to assist the NRCS and local sponsor(s) in determining future actions concerning potential rehabilitation of the dam to extend the service life of the dam and meet current safety criteria.

The Watershed Protection and Flood Protection Act (Section 14 of PL-83-566, as amended) authorizes funding and technical assistance to rehabilitate aging flood control dams originally built with assistance of the USDA Watershed Programs. Sponsors of these dams may apply for assistance to extend the project service life and ensure that the facility meets applicable safety and performance standards. If the project is eligible for rehabilitation assistance, the NRCS may provide funding for 65 percent of the total rehabilitation project costs; the project sponsors are responsible for the remaining 35 percent. Technical assistance by NRCS for planning and design of the rehabilitation project is provided at no cost to project sponsors.

## **2. Project Setting and History**

The original New Creek – White’s Run Subwatersheds Work Plan Agreement was signed on March 11, 1957. The New Creek Subwatershed of the Potomac River Watershed was planned and constructed in accordance with provisions of PL-534, approved December 22, 1944. The project Work Plan was supplemented four times; Supplemental Work Plan Agreement No. 1 signed in December 1959, Supplemental Work Plan Agreement No. 2 signed in January 1961, Supplemental Work Plan Agreement No. 3 signed in October 1961, and Supplemental Work Plan Agreement No. 4 signed in August 1991. The Potomac Valley Conservation District, the West Virginia State Conservation Committee, and the City of Keyser, WV are the sponsors of the project.

The purpose of the plan for New Creek Subwatershed was to outline land treatment and structural measures necessary to achieve the maximum practical erosion control and alleviate flood damage. Installation of planned structural measures were to assist in providing floodwater protection to dwellings, roads, fields, crops, and businesses, and to permit more intensive land use by reducing damage to land in the flood regions and also make uplands more attractive and productive. A total of 9 floodwater retarding dams were constructed on tributaries within the New Creek Watershed.

New Creek Site 17 is located on Ash Spring Run in Mineral County approximately 7 miles south of Keyser, WV. The location of New Creek Site 17 is shown on the Project Map for the New Creek Watershed Presented on Exhibit 1. An aerial photo and USGS quadrangle of New Creek Site 17 are presented on Figures 1 and 2, respectively.



Engineering design data and other reference data were collected and reviewed. The following is a list of data sources reviewed for this assessment report.

1. Original Work Plan and Subsequent Supplements (12/1956, 12/1959, 05/1961, 10/1961, 05/1991)
2. As-Built Drawings (1960)
3. Design Report Sections (Geology, 1959) (Soil Mechanics, Hydraulic Design, 1960)
4. Inspection Records (2008, 2009, 2010)
5. O&M Agreement and Amendments (01/1959, 02/1960, 01/1964, 12/2002)
6. Failure and Risk Index Spreadsheet (2011)
7. New Creek Sub-watershed Map (2010)
8. Emergency Action Plan (12/2007)

New Creek Site 17 is a single purpose flood control dam designed by the SCS (now NRCS), Morgantown, West Virginia. The dam and its appurtenances consist of a 1,735-foot long, zoned earthfill embankment with a maximum height of 68.3 feet above the invert of the principal spillway. The dam has two spillways; a two-stage principal spillway and an open channel vegetated auxiliary spillway. The auxiliary spillway crest is approximately 7.2 feet below the top of the dam. Both spillways are uncontrolled. All inflow is discharged through the principal spillway until the pool level reaches the level of the auxiliary spillway crest. A drawdown gate was provided to lower or drain the reservoir. The principal spillway conduit consists of a 24-inch diameter reinforced concrete, steel cylinder type pre-stressed pressure pipe conforming to AWWA-C301 standards. The principal spillway conduit was constructed with a concrete cradle with reinforced concrete anti-seep collars.

A summary of specific design data is presented in Table 1. Selected as-built drawings are presented in Appendix A.

### **3. Site Inspection Summary and Operation and Maintenance**

William Franz, P.E., P.G.; Gregory Richards, E.I.T.; and Joe Bell, E.I.T. of Gannett Fleming, Inc. conducted a site inspection of New Creek Site 12 on September 2, 2010. The WV-ENG-105, Formal Dam Inspection Checklist was used to record findings and is presented in Appendix B. General photographs of the dam site (Photos 1-6) and photographs of deficiencies (Photos 7-16) noted during the site inspection are also presented in Appendix B. Additional photos taken during the field review are furnished in the Supporting Data Folder on a CD. With the exception of several ongoing maintenance items noted below, the dam was found to be in good condition.

The grass cover on the upstream and downstream slope of the dam embankment has not been mowed for several years as evidenced by brush and small trees on both the upstream and downstream slopes. The downstream slope was constructed with a steep 2:1 slope and armored in some areas with large cobbles. Due to the inability to mow the areas covered in cobbles, vegetation has become very dense in these areas. Additionally, the slope in these areas seems very irregular which suggests there has been some creep of the downstream slope. Large trees were also observed to be encroaching on the abutment contacts of the dam.



Figure 1. Aerial Photo of New Creek Site 17




Figure 2. USGS Quadrangle of New Creek Site 17



**Table 1**  
**As-Built Design Data for New Creek Site 17**

Description	Value
<b>General Data</b>	
Year Designed	1959
Year Constructed	1960
Purpose	Flood Control
Original Hazard Classification	High (Class C)
Current Hazard Classification	High (Class C)
Design Life	50 years (2010)
Design Drainage Area	1,086 Acres (1.7 Mi <sup>2</sup> )
Dam Height (Along Centerline)	57.3 Feet
Maximum Dam Height	68.3 Feet
Embankment Length	1,735 Feet
Embankment Top Width	19 Feet
Embankment Upstream Slope	3H:1V
Embankment Downstream Slope	2H:1V
<b>Critical Elevations (MSL)</b>	
Top of Dam	1143.3 Feet
Auxiliary Spillway Crest	1136.1 Feet
PSW Weir	1128.4 Feet
Normal Pool (50-Year Submerged Sediment)	1104.12 Feet
PSW Conduit Outfall Invert	1075.01 Feet
PSW Outlet Channel Invert	1074.0 Feet
<b>Storage Capacities</b>	
Sediment Storage (50-Year Submerged & Aerated Sediment)	35 Acre-Feet
Normal Pool (50-Year Submerged Sediment)	25.5 Acre-Feet
Auxiliary Spillway Crest	384.5 Acre-Feet
Top of Dam	557.7 Acre-Feet
<b>Pool Surface Areas</b>	
Normal Pool	3.81 Acres
Auxiliary Spillway Crest	20.87 Acres
<b>Other Features</b>	
Principal Spillway Orifice Size	16 Inch Dia.
Principal Spillway Conduit Diameter	24 Inches
Principal Spillway Conduit Length	280.33 Feet
Principal Spillway Weir Crest Length	12-Feet (Total)
Auxiliary Spillway Width	200 Feet



Bare earth tire ruts were observed on the crest of the dam as well as on the auxiliary spillway training dike and the left side of the downstream slope. An animal burrow was observed near the toe of the downstream embankment. A small, wooden fence runs through the channel of the auxiliary spillway.

The principal spillway conduit outlet shows signs of significant deterioration including a fracture about 4 feet long. The outlet and plunge pool are surrounded and obstructed by thick, woody vegetation. A seep was observed beneath the cradle of the principal spillway outlet conduit. The seep was visibly flowing. No drains were observed at the site.

The concrete principal spillway riser structure appears to be in good condition and operating as designed. No external evidence of cracking or deterioration of the concrete was observed. The lower level trash rack and drawdown handwheel show signs of corrosion and need to be painted. There is also some minor debris on the lower inlet trash rack as well as a large tree branch lodged in the principal spillway riser structure.

Items inaccessible for inspection include the buried exterior section of the riser structure, control valve, interior of the riser structure, submerged portions of the pond drain intake, and the interior of the principal spillway conduit.

In addition to the site inspection, a video inspection of the principal spillway conduit as provided by the NRCS was reviewed. The ROVER inspection of the principal spillway conduit was performed on September 18, 2002 and revealed visible evidence of wear of the concrete lining throughout the length of the conduit. The inspection also showed some joint separation.

Items of deferred maintenance include removal of woody vegetation from the embankment and auxiliary spillway, filling groundhog holes, filling and seeding bare earth tire ruts, removal of small fence in the auxiliary spillway, repairing the concrete lining of the principal spillway outlet conduit, clearing vegetation and trees away from the plunge pool area, painting the lower trash rack and drawdown handwheel, and clearing debris from the riser structure. Gates should also be replaced in order to reduce motorized traffic across the dam crest. In addition to these maintenance items, the seep below the principal spillway should be monitored. Also, long-term maintenance issues as well as possible stability concerns for the downstream slope of the embankment should be investigated and addressed.

It should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. It is also important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Continued care and inspection are necessary to detect unsafe conditions.

#### **4. Hydrologic and Hydraulic Analyses**

Hydraulic analyses were conducted to determine whether the dam meets NRCS and WVDEP current criteria. NRCS design precipitation and other hydrologic parameters have



become more stringent since the dam was designed in the 1950s. As part of this assessment, updated hydrologic and hydraulic analyses using the NRCS SITES model were performed to determine the required auxiliary spillway crest and top of dam elevations. Structure geometry and reservoir storage inputs as well as watershed hydrologic characteristics for the model were obtained from as-built drawings and other design documents provided by the West Virginia NRCS. The SITES analyses involved evaluation of the top of dam elevation for both the short duration (6-hour) storm and the long duration (24-hour) storm in accordance with procedures outlined in the latest version (July 2005) of TR-60. The elevation of the auxiliary spillway crest was also evaluated for the 100-year event. The SITES output for as-built, Class C (*high hazard*) criteria for the 6-hour and 24-hour duration storms and the auxiliary spillway crest elevation are presented in Appendix C. A side-by-side comparison of key SITES model input and output for the different scenarios analyzed is presented in Table 2.

**Table 2**  
**Side-By-Side Comparison of Key SITES Model Input and Output**

Parameter	Original Class C 1959 Design	100-Year ASW Crest	6-hr Class C Top of Dam	24-hr Class C Top of Dam
<b>Key Input Data</b>				
Watershed Area	1,086 Acres	1,086 Acres	1,086 Acres	1,086 Acres
Weighted Curve Number	72.0	72.0	72.0	72.0
Time of Concentration, T <sub>c</sub>	0.78 Hours	0.78 Hours	0.78 Hours	0.78 Hours
100-Year Rainfall (P-100)	- Inches	5.82 Inches	3.8 Inches	5.82 Inches
Freeboard Rainfall (P-FB)	26.33 Inches	-	27.3 Inches	34.8 Inches
<b>Key Output Data</b>				
ASW Crest Elevation	1136.1 Feet	<b>1130.06 Feet</b>	1136.10 Feet	1136.10 Feet
Top of Dam Elevation	1143.3 Feet	-	1143.91 Feet	1141.15 Feet
<b>Freeboard</b>	-	-	<b>-0.61 Feet</b>	<b>2.15 Feet</b>

The following can be concluded based on the analysis results summarized in Table 2:

1. The Auxiliary Spillway crest is 6.04 feet higher than required using the 100-year flood activation criteria.
2. For a Class C (*high hazard*) structure, the dam would be overtopped and would need to be raised 0.61 feet to pass the 6-hr Freeboard Hydrograph without overtopping.

## 5. Spillway Integrity Analyses

Preliminary auxiliary spillway integrity analyses were also performed as part of this assessment using the SITES program. Very little subsurface information is available from which to develop a representative geologic profile of the most erodible section through the auxiliary spillway. The assumed geologic profile of the auxiliary spillway was developed using as-built drawings, geology and soils design reports, and supplemental reports from the United States Geological Survey and the West Virginia Geological and Economic Survey.



The geology of the auxiliary spillway for the SITES integrity analysis was assumed to consist of soil from the crest of the spillway down to elevation 1125 feet. Shale is located below the soil down to the valley floor. The assumed material properties for the preliminary assessment of the spillway integrity are presented in Table 3. A schematic profile of the auxiliary spillway obtained from the SITES output is presented on Figure 3.

**Table 3**  
**Assumed Parameters for Auxiliary Spillway Integrity Analysis**

Material Description	Assumed ASW Material Erosion Parameters				
	Dry Density (lbs/ft <sup>3</sup> )	Headcut Index (K <sub>h</sub> )	Percent Clay	Plasticity Index	D <sub>75</sub> / Rep. Dia.(in)
Soil/Ground	125	0.37	28	12	0.004
Shale	110	2	0	0	0.5




Figure 3. Plot of Auxiliary Spillway Profile and Extent of Erosion from Integrity Analysis for 24-hour Class C Freeboard Hydrograph (PMF) Obtained from SITES Model Output

The SITES auxiliary spillway analysis shows only minor damage for both the 6-hour and 24-hour duration storm events. Photos 9 and 16 show features including trees and a small, wooden fence observed in the auxiliary spillway during the site visit that can accelerate erosion of the spillway. These features have not been incorporated in the SITES auxiliary spillway



analysis but should be considered in evaluating the overall integrity of the spillway. The SITES output for both the 6-hour and 24-hour storms for as-built, Class C criteria are presented in Appendix C. The electronic input files for the SITES model are furnished in the Supporting Data Folder on a CD.

## **6. Breach Inundation Mapping and Hazard Classification Summary**

A dam breach hydraulic analysis was performed using the U.S. Army Corps of Engineers' HEC-RAS computer model in order to determine the downstream inundation limits of the flood wave created by a sudden breach of the dam. A field assessment of downstream structures located within the path of the flood wave was also made to verify the current hazard classification. The hazard classification evaluation consisted of evaluating the downstream area within the breach inundation zone. The dam was then classified according to West Virginia State Dam Safety definitions and NRCS definitions in NEM, Part 520, Subpart C – Dams.

The inflow hydrograph, reservoir stage-storage relationship, and other inputs used to describe the dam in the HEC-RAS model were obtained from the 6-hour FBH SITES output and as-built drawings. The dam breach parameters, including the time to breach, breach bottom width and side slopes were determined by trial and error until the peak breach discharge criteria specified in TR-60 was satisfied. The minimum and maximum peak breach discharges using TR-60 criteria were computed to be 87,332 cfs and 123,323 cfs, respectively. Assuming a complete breach of the dam occurs within 4.8 minutes, a peak breach discharge of approximately 113,000 cfs was computed using the HEC-RAS model. The height of the breach flood wave at the dam site, from the top of the dam to the valley floor would be approximately 66 feet.

The HEC-RAS dam breach analysis and downstream unsteady flow modeling of the flood wave was performed using a three (3) meter Digital Elevation Model (DEM) and SAMB Orthophotos to obtain the cross sections and Manning's "n" values necessary for modeling the channel and flood plain. The HEC-RAS model of the downstream area at the confluence of Ash Spring Run with New Creek was treated as a junction so that the flood wave could be modeled as propagating both upstream and downstream of the junction. The additional storage attenuation of the flood wave within the reach immediately upstream of the junction can be an important feature of the hydraulic analysis. Without this feature, the downstream inundation limits can be overestimated.

The extent of the breach analysis was greater than that shown on the existing inundation map included in the Emergency Evacuation Plan for this structure. The breach analysis was based upon the FBH storm for a Class C dam with assumed failure occurring at the top of dam elevation. The FBH storm was only assumed to occur in the watershed upstream of the dam with normal base flow of approximately 300 cfs occurring downstream of the dam. Flood elevations were tracked downstream until they came largely within the stream bank or when the flow rate was less than 10 percent of the peak breach flow rate at the dam.

For New Creek Site 17, the inundation mapping was extended to the city of Keyser, approximately 6.5 miles downstream of the dam, until the flood wave was largely within the banks of New Creek. According to the HEC-RAS dam breach model, the peak flow rate of the



breach flow or flood wave at Keyser is approximately 14,800 cfs or 13 percent of the peak breach flow at the dam. The resulting inundation limits in the vicinity of Keyser were compared with the inundation limits shown on the existing detailed FEMA Flood Insurance maps for the same area for the 100-year and 500-year flood events. At Keyser, the peak 100-year and 500-year FEMA flood flows were estimated to be 10,610 cfs and 15,710 cfs, respectively. The peak FEMA 100- and 500-year flood elevation near the center of Keyser were reported to be 809.5 feet and 813 feet. The peak dam breach flood elevation at the same location was computed to be 807.5 feet. A side by side comparison of the dam breach inundation mapping and the FEMA Flood Insurance mapping at Keyser is presented in Figure 4.

Homes, businesses, road crossings, bridges, farms and commercial buildings, utilities and other structures located within the dam breach inundation limits were identified and photographed. All photographs were tagged electronically with their date, time, longitude and latitude using GPS. This information was used to create a GIS database to help quantify the flood impacts and persons at risk.

The limits of the maximum pool elevation and the downstream inundation were plotted in AutoCAD on both an orthophoto base map and a USGS Quadrangle base map, and are presented on Exhibits 2 and 3, respectively. The locations of all cross sections used in the HEC-RAS model are also shown Exhibits 2 and 3. All associated HEC-RAS, AutoCAD, and other supporting computer files are furnished in the Supporting Data Folder on a CD. A GIS database containing the downstream inundation limits and the photographs of all inundated features within the downstream inundation limits is also provided on a CD.

According to West Virginia State Dam Safety definitions and NRCS definitions in NEM, Part 520, Subpart C – Dams, *high hazard* dams (Class 1 or Class C) are those dams located where failure may cause loss of human life or serious damage to homes, commercial or industrial buildings, main highways or railroads, or important public utilities. This classification must be used if failure may result in the loss of human life. Existing and future downstream development including controls for future development must be considered when classifying the dam.

New Creek Site 17 was designed in 1959 as a *high hazard* (Class C) structure. Based on the inundation mapping presented on Exhibits 2 and 3, and the downstream reconnaissance of the area within the inundation zone, this classification is found to be appropriate. Sudden failure of New Creek Site 17 during the FBH event impacts considerable downstream dwellings, road crossings/bridges, commercial buildings and other structures, and meets both the loss of life and property damage criteria for a high hazard dam.

Two dwellings were identified within the downstream inundation zone that are less than 500 feet from the toe of the dam. Many other dwellings, including the City of Keyser, approximately 6.5 miles downstream, would clearly be impacted by a flood wave that overflowed the channel banks.

A total of approximately 457 dwellings were judged to experience flooding of the adjacent ground by a depth of more than 3 feet based on the aforementioned dam failure



hydraulic analysis. The corresponding persons at risk (PAR) assuming an average of 2.5 persons per dwelling is 1143 persons.




Figure 4. Side by Side Comparison of Floodplain Boundaries from the 1991 FEMA Flood Insurance Study (left) and the 2011 Gannett Fleming Dam Breach Study (right) at Keyser, West Virginia.

It should be noted that according to the HEC-RAS model results, it will take about 2 hours for a flood wave created by a sudden failure of New Creek Site 17 to reach its peak flood



level at Keyser. There is, therefore, a limited amount of warning time available which significantly decreases the probability of survival for persons at risk that are located in the downstream reaches of the inundation area.

## **7. Review of Available Geotechnical Information**

Available geotechnical information was reviewed with respect to items that are considered in the “*Evaluation of Potential Rehabilitation Projects-Priority Ranking Spreadsheet*”. This information included the Geology and Soils Reports (1959, 1960), as-built plans (1960), and Phase I Inspection Report prepared by Berger Associates for the Huntington District of the U.S. Army Corps of Engineers (1981).

The 1960’s time period for design and construction predates the full development of several current NRCS design criteria. Two important design criteria include drain/filter compatibility and seepage control for principal spillway conduits. The manuals that define these two design methodologies, Gradation Design of Sand and Gravel Filters and Filter Diaphragms, were first published in 1994 and 2007, respectively. The compatibility of adjacent embankment zones is another design criteria that has developed since the 1960’s and has become an essential step in the design process for earthen dams.

The embankment relies entirely on the downstream rock fill toe to filter, collect, and convey seepage. The rock fill material was obtained from removing rock larger than 6 inches from the embankment fill. The as-built plans show no internal drain. An internal drain is typically built on the embankment/foundation contact about midway between the crest and downstream toe. The lack of an internal drain, which can serve the additional role of a filter diaphragm along the principal spillway conduit, is a very significant omission from the design.

Another design issue that can only be evaluated with an additional subsurface investigation is the compatibility of the clayey central core to the downstream shale shell, the compatibility of the shale shell to the rock fill toe, and the rock fill toe to the foundation soils. Transition zones which are required by current design criteria were not constructed at the contacts between zones.

Slope stability analyses performed as part of the original design were not available. However, a downstream slope stability analysis was performed in conjunction with the Phase I inspection. Shear strengths were taken from the original Soils Report and the phreatic surface was represented by a straight line between the sediment pool and the downstream toe. As discussed in Section 3, the steep 2H:1V downstream rock fill slope is very irregular. At a minimum this would imply that significant creep movement has occurred. The extreme vegetation covering the slope limited observation to fully evaluate the extent of movement.

The seepage control deficiencies and the possibility of inadequate slope stability require a thorough geotechnical assessment. The assessment should include a subsurface investigation to determine the geotechnical characteristics of the foundation and embankment. The dam has no instrumentation to monitor phreatic levels, seepage discharge, or surface movement.



Review comments related to the geotechnical factors in the “*Evaluation of Potential Rehabilitation Projects-Priority Ranking Spreadsheet*” are presented in Appendix D. Also included in the appendix is a copy of the spreadsheet as completed by the WV NRCS.

## **8. Failure and Risk Indexes**

The structure’s risk of failure and the consequences of failure were evaluated by the WV NRCS by completing the “Evaluation of Potential Rehabilitation Projects-Priority Ranking Spreadsheet” (Exhibit 508.1 of the NRCS-National Watershed Manual) to determine whether the dam qualifies for rehabilitation as per Section 508 Subpart E of the National Watershed Manual. Based on the completed spreadsheet, the total failure index computed by the NRCS for New Creek Site 17 is 273, with a total risk index of 12,482. A copy of the spreadsheet completed by the WV NRCS is included in Appendix D.

## **9. Discussion of Potential Rehabilitation Alternatives**

In order to satisfy Class C (*high hazard*) design criteria, the only current deficiency identified in the preliminary SITES analysis is the overtopping of the dam. The preliminary SITES integrity analysis determined that the auxiliary spillway would experience an acceptable amount of damage during passage of the Freeboard Hydrograph. Therefore, armoring of the spillway will not be required.

It is noted that the dam assessment and spillway integrity analysis were performed using limited information about the subsurface properties of the dam embankment and auxiliary spillway profile. Some design features within the embankment, particularly drain/filter compatibility, seepage control, and compatibility between adjacent embankment zones as discussed in Section 7 of this report, do not meet current NRCS design criteria. Full evaluation for compliance to current criteria cannot be confirmed without a subsurface investigation and subsequent analyses and are not included herein as deficiencies requiring rehabilitation.

Modifications modeled with the SITES program include lowering the auxiliary spillway, widening the auxiliary spillway, and armoring the embankment so that it could be overtopped without eroding. Table 4 provides a summary of the results of SITES runs where the elevation and width of the auxiliary spillway were varied and the dam was armored so that it could be overtopped.

## **10. Cost Estimates for Rehabilitation Alternatives**

Based on preliminary information, planning level cost estimates were prepared for the four alternatives listed in Table 4 and are presented in Table 5. Decommissioning or breaching the dam was included as an alternative in Table 5. The estimates assume that the auxiliary spillway will not need to be armored to prevent spillway breaching and that major expenditures to address potential embankment deficiencies are not required. Cost estimates are based on approximate quantities and construction prices from similar projects.

Combinations and permutations of the alternatives presented in Table 4, and other alternatives can be explored and refined during subsequent planning phases for this project to



**Table 4**  
**Potential Modifications to Bring New Creek Site 17**  
**Into Compliance with NRCS Class C Structure Design Criteria**

Alternative	Alternative Description	Lower ASW Crest Elevation (Feet)	ASW Width (Feet)	Amount Dam would Need to be Raised (Feet)	Overtopping Depth (Feet)
1	Raise Dam	0	200	<b>0.61</b>	0
2	Lower ASW Crest <sup>(1)</sup>	<b>0.64</b>	200	0	0
3	Widen ASW Crest	0	<b>235</b>	0	0
4	Armor Embankment	0	200	0	<b>0.48</b>

(1) *Would result in loss of some flood control benefits. However, the ASW would still meet the 100-year flood activation criteria according to current design standards if lowered by 0.64 feet.*

**Table 5**  
**Planning-Level Cost Estimates for Modifications to Bring**  
**New Creek Site 17 into Compliance with NRCS Class C Design Criteria\***

Alternative	Alternative Description	Estimated Total Project Cost
1	Raise Dam <sup>(1)</sup>	\$2,600,000
2	Lower ASW Crest <sup>(2)</sup>	\$150,000
3	Widen ASW	\$300,000
4	Armor Embankment	\$8,600,000
5	Decommission/Breach Dam	\$1,500,000

\* *Some design features within the embankment may not meet current NRCS design criteria. Compliance of these features cannot be confirmed without further analysis and are not included herein as deficiencies requiring rehabilitation.*

(1) *This cost represents a standard approach to raising a dam and includes the installation of a filter, drains, and fill across the entire downstream slope. Because the dam needs to be raised by only 0.61-foot, less costly alternatives such as regrading or narrowing the crest, steepening the slopes, or the installation of a parapet wall should be investigated.*

(2) *Would result in loss of some flood control benefits. However, the ASW would still meet the 100-year flood activation criteria according to current design standards if lowered by 0.64-foot.*



obtain the most cost effective solution. For example, a combination of widening the auxiliary spillway and raising the dam to achieve a balance of materials can be evaluated. As an option to Alternative 2 (lower ASW crest), if it is desired that the current flood storage capacity of the existing dam and reservoir be maintained, fuse plugs or fuse gates could be incorporated into the lowered auxiliary spillway crest design. The fuse plugs or fuse gates could be divided into multiple individual bays such that they would be activated or eroded sequentially and only as needed.

## **11. Conclusions and Recommendations**

**11.1 Operations and Maintenance.** New Creek Site 17 was observed to be in good condition with several maintenance deficiencies that need to be addressed. These include removal of woody vegetation from the embankment and auxiliary spillway, filling groundhog holes, filling and seeding bare earth tire ruts, removal of small fence in the auxiliary spillway, repairing the concrete lining of the principal spillway outlet conduit, clearing vegetation and trees away from the plunge pool area, painting the lower trash rack and drawdown handwheel, and clearing debris from the riser structure. Gates should also be replaced in order to control unauthorized motorized traffic across the dam crest. In addition to these maintenance items, the seep below the principal spillway should be monitored. Also, long-term maintenance issues as well as possible stability concerns for the downstream slope of the embankment should be investigated and addressed.

**11.2 Additional Studies.** Subsurface investigations to more accurately quantify conditions within the embankment, foundation, and auxiliary spillway are recommended. This information is important to confirm that the embankment meets current design criteria and to more accurately evaluate the integrity of the auxiliary spillway. The combination of the lack of an embankment drain and an irregular 2H:1V downstream slope provides a strong incentive to complete a subsurface investigation to evaluate stability. The extreme vegetation on the downstream slope will probably require an initial clearing and grubbing effort. Items not readily accessible for inspection such as the inside of the principal spillway conduit and riser structure, and the buried exterior of the riser and drain control valve should also be assessed.

**11.3 Hazard Classification.** Based on the inundation mapping prepared as part of this study and the downstream reconnaissance of the area within the inundation zone, the classification of New Creek Site 17 as a high hazard structure is found to be appropriate. Sudden failure of New Creek Site 17 during the FBH event impacts considerable downstream dwellings, road crossings/bridges, commercial buildings and other structures, and meets both the loss of life and property damage criteria for a high hazard dam.

**11.4 Design Deficiencies.** New Creek Site 17 not meet current NRCS design criteria for a Class C (*high hazard*) structure. The only identified design deficiency is the overtopping of the dam during passage of the FBH. Other deficiencies may exist related to geotechnical issues with the embankment or features that were not inspected.







**11.5 Failure and Risk Indexes and Priority Ranking of Rehabilitation Project.** The total failure index for New Creek Site 17 as indicated in the spreadsheet prepared by the WV NRCS is 273, with a total risk index of 12,482.


**11.6 Rehabilitation Project.** Major modifications to New Creek Site 17 are needed to bring the dam into compliance with current NRCS high hazard dam design criteria, for the known deficiencies. Of the alternatives listed in Table 5, a combination of lowering or widening the auxiliary spillway, and raising the dam appear to offer the best value. A planning level total project cost to make structural modifications to the dam to meet current NRCS design criteria without compromising current flood control benefits is estimated at \$300,000. This estimate assumes that the auxiliary spillway will not need to be armored to prevent spillway breaching and that major expenditures to address potential embankment deficiencies are not required, as discussed in Section 9 and Section 11.2.

# NEW CREEK WATERSHED MINERAL AND GRANT COUNTY, WEST VIRGINIA



### LEGEND

-  Structure Number
-  U.S. Numbered Highway
-  WV Numbered Highway
-  WV County Numbered Route



W:\2016\Active Jobs\52299 - WV NRCS 2010 Contract\05 Working\41 Dam Assessments\1 - CAD\New Creek Site 17\New Creek Site 17 Foundation Map.dwg  
Plot Date: 1/2/2011 2:40 PM Plotted By: Miller, Brian S.



**NEW CREEK  
SITE 17 DAM**

**NEW CREEK**

**KEYSER**

**CLAYSVILLE**

**DAM BREACH INUNDATION MAP**

NEW CREEK SITE 17  
NIDID: WV 05706  
MINERAL COUNTY, WEST VIRGINIA



**LEGEND**


- HEC-RAS CROSS SECTIONS
- INUNDATION AREA
- FLOOD POOL



PREPARED BY:  
**Gannett Fleming**  
207 SENATE AVENUE, CAMP HILL, PA. 17011

EXHIBIT  
**2**  
NOV. 2010

W:\12\Active Jobs\52298 - WV NRCS 2010 Contract\05 Working\41 Dam Assessments\1 - CADD\New Creek Site 17\New Creek Site 17 Foundation Map.dwg  
Plot Date: 1/2/2011 2:28 PM Plotted By: Miller, Brian S.



NEW CREEK  
SITE 17 DAM

CLAYSVILLE

NEW CREEK

**DAM BREACH INUNDATION MAP**

NEW CREEK SITE 17  
NIDID: WV 05706  
MINERAL COUNTY, WEST VIRGINIA



**LEGEND**

- HEC-RAS CROSS SECTIONS
- INUNDATION AREA
- FLOOD POOL



PREPARED BY:  
**Gannett Fleming**  
207 SENATE AVENUE, CAMP HILL, PA. 17011

EXHIBIT  
**3**  
NOV. 2010



---

---

Appendix A  
Selected As-Built Drawings

---

---

# "AS BUILT"

24

## POTOMAC RIVER FLOOD PREVENTION PROJECT NEW CREEK SITE NE-P # 17 KEYSER, WEST VIRGINIA

DRAINAGE AREA	1086.0 ACRES
FLOODWATER DETENTION CAPACITY	<del>348</del> 548 AC. FT.
SEDIMENT STORAGE	24.5 AC. FT.
SEDIMENT POOL AREA	<del>9.1</del> 0 ACRES
HEIGHT OF DAM	57.3 FEET
PRINCIPAL SPILLWAY DIAMETER	24.0 INCHES

BUILT BY THE  
U. S. DEPARTMENT OF AGRICULTURE  
SOIL CONSERVATION SERVICE

COOPERATING WITH  
POTOMAC VALLEY  
SOIL CONSERVATION DISTRICT

### INDEX

- SHEET 1 COVER SHEET
- SHEET 2 PLAN OF DAM AND STORAGE AREAS
- SHEET 3  $\phi$  LAYOUT SKETCH
- SHEET 4 GEOLOGIC PROFILES AND TYPICAL SECTION OF FILL
- SHEET 5 PROFILE ALONG  $\phi$  PRINCIPAL SPILLWAY
- SHEET 6 STRUCTURAL DIMENSIONS & TRASH RACK DETAILS
- SHEET 7 REINFORCING STEEL DETAILS
- SHEET 8 MISCELLANEOUS DETAILS
- SHEET 1-4 HYDROGRAPHS

# "AS BUILT"

COVER SHEET POTOMAC RIVER BASIN FLOOD PREVENTION PROJECT FLOOD DETENTION SITE NE-P # 17 KEYSER, WEST VIRGINIA			
U. S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE			
Designed by H. DUBLOFSKY - E.D.M.	Date DEC '59	Approved by <i>William W. Smith</i> CHIEF OF E. & W. P. UNIT	
Drawn by M. NIKOLICH	Date JAN '60	Checked by <i>Harold M. R. Hood</i> STATE CONSERVATION ENG.	
Checked by W. J. CARROLL	Date FEB '60	Sheet No. 8	Drawing No. WV-433-P


**NOTE:**

ALL LAND AFFECTED OWNED BY  
A. J. PANCAKE JR.

# “AS BUILT”

**GENERAL NOTES:**

- 1 ALL COMPACTED FILL SHALL BE TYPE 1-2 OR 1-3 AS SHOWN ON SHEET & W.A. SPEC. 5-58 (A)
- 2 AREA UNDER THE DAM, BORROW AREA AND EMERGENCY SPILLWAY TO BE CLEARED AND GRUBBED. **27.1 ACRES** (SEC. 1-3)
- 3 TOPSOIL REMOVED AND STOCKPILED IN STRIPPING OPERATIONS SHALL BE SPREAD ON THE FILL, EMERGENCY SPILLWAY AND BORROW AREAS AS DIRECTED BY THE ENGINEER. (SEC. 1-3)
- 4 ALL CONCRETE SHALL BE CLASS "B" AND OF THE TYPE NOTED IN 10-11-19
- 5 PORTLAND CEMENT TYPE 20 OR TYPE 1 WITH AN AIR-ENTRAINING ADMIXTURE, SHALL BE USED. SPEC. 10-11 & 10-15 (ASSEMBLY) WAS
- 6 ALL REINFORCING STEEL PLACED IN CONCRETE POURED AGAINST THE GROUND SHALL HAVE A MIN. OF 3" CLEAR COVER WHERE FORMS ARE USED ALL BARS SHALL HAVE A MIN. OF 2" CLEAR COVER
- 7 EXPOSED EDGES OF CONCRETE TO HAVE A 3/8" INCH CHAMFER.
- 8 RIPRAP SHALL BE WELL GRADED FROM A MIN. SIZE OF 1 1/2" TO A MAX. OF 18" ALL RIP-RAP SHALL BE PLACED WITH THE LONG DIMENSION PERPENDICULAR TO THE LINE OF FLOW. SPEC. 7-58
- 9 ALL METAL FABRICATION THAT IS NOT GALVANIZED, OR EMBEDDED IN THE CONCRETE **MUST BE PAINTED.** (M.C. 11-11 & 11-55) WAS



FOR TYPICAL SECTION, SEE SHEET 2 OF 2  
EXCAVATE OUTLET CHANNEL - 250'; SLOPE 2.5% 383

FOR CURVE LAYOUT DETAILS SEE SHEET 2 OF 2

# “AS BUILT”



RIE-RAP TO BE HAND PLACED ON EDGE.  
TYPICAL SECTION OF RIP-RAP GUTTER  
SCALE: 1" = 1'-0"

SCALE: 1" = 100'

PLAN OF DAM AND STORAGE AREAS  
POTOMAC RIVER BASIN  
FLOOD PREVENTION PROJECT  
FLOOD DETENTION SITE NE-P #17  
KEYSER, WEST VIRGINIA

U.S. DEPARTMENT OF AGRICULTURE  
SOIL CONSERVATION SERVICE

Designed by JAMES O'BRIEN  
Checked by LEROY FRIEL  
Date: SEPT. 1971  
Scale: 1" = 100'

Approved by: *[Signature]*  
Checked by: *[Signature]*  
Date: 10/28/71  
Scale: 1" = 100'

Drawn by: LEE R. GREEN  
Checked by: *[Signature]*  
Date: 11/10/71  
Scale: 1" = 100'


Drawn by: *[Signature]*  
Checked by: *[Signature]*  
Date: 11/10/71  
Scale: 1" = 100'

NOTE: TOTAL CLEARING & GRUBBING - **27.1 ACRES**


NOTE: PORTION OF BORROW IS REQUIRED TO BE TAKEN IN HEIGHTS AND LOCATION AS GIVEN IN TABLE BELOW. (APPROX. 9" IN DEPTH OVER AREA)

BETWEEN ELEV.	CU. YDS
1090.0 & 1104.1	27,100
1104.1 & 1118.4	68,750
1118.4 & 1132.7	19,650
1132.7 & 1147.0	10,500
<b>124,600 TOTAL</b>	

SEE STORAGE CHARTS ON HYDRO GRAPHS.



AREA CLEARING & GRUBBING 117.0 AC



**CURVE DATA**

R = 162'	M = 123.47
Δ = 155° 00'	E = 181.97
L = 852.80'	PC = 4+08.0
LS = 668.90'	PI = 14+81.94
T = 873.94'	PT = 14+81.94


	STATIONS IN CURVE	DEFLECTION	CURVED DISTANCE
	PC 4+08.0	0°-0'-0"	0.00
	7+08	7°-59'-50"	99.68
	8+08	15°-49'-40"	99.68
	9+08	23°-04'-30"	99.68
	10+08	31°-33'-28"	99.68
E. OF BATH DEAN	10+34.83	35°-50'-21"	99.68
	11+08	39°-54'-10"	99.68
	12+08	47°-18'-00"	99.68
	13+08	55°-03'-50"	99.68
	14+08	63°-18'-44"	99.68
PT	14+81.94	67°-30'-0"	12.90

**"AS BUILT"**


**LAYOUT SKETCH**  
 NEW GALEA WATERWAYS, FLOOD PREVENTION PROJECT  
 DETENTION RESERVOIR SITE #17  
 KEYSER, WEST VIRGINIA

**U.S. DEPARTMENT OF AGRICULTURE  
 SOIL CONSERVATION SERVICE**

Designed by <b>JAMES E. STEFFEY</b>	Date <b>SEPT. 93</b>	Approved by
Drawn by <b>STEFFEY</b>	Scale <b>5/8"=1'</b>	File #
Checked by <b>CHARLES H. CARROLL</b>	Plot No. <b>103</b>	Sheet No. <b>3</b>
Drawn by <b>JAMES</b>	Project No. <b>WV-433-P</b>	Scale <b>1"=100'</b>



DATE OF GEOLOGICAL INVESTIGATION - OCTOBER, 1997




**"AS BUILT"**

GEOLOGIC PROFILES & TYPICAL SECTIONS  
 FLOOD CONTROL BASIN  
 FLOOD PREVENTION PROJECT  
 FLOOD DETENTION SITE NE-P-11  
 KEYSER, WEST VIRGINIA

**U.S. DEPARTMENT OF AGRICULTURE  
 SOIL CONSERVATION SERVICE**

Project: KEYSER, WEST VIRGINIA  
 Date: OCT. 20, 1997  
 Drawn by: KESSEL - JAMES  
 Scale: 1" HORIZ. = 20' VERT. = 10'






TOP VIEW




SECTION ON CENTERLINE

DETAILS OF REINFORCED CONCRETE RISER & ANTI-VORTEX DEVICE

SCALE 1/4" = 1'-0" (ENC. H, I, K, L, M, N)



REAR ELEVATION




DETAILS OF HIGH STAGE TRASH RACK

SCALE 3/8" = 1'-0"

BILL OF MATERIALS			
ITEM	SIZE	LENGTH	NO. REQ.
GRV PIPE - STD. THK.	2" DIA.	8'-0"	2
CALV. PIPE - STD. THK.	3" DIA.	0'-10"	12
CALV. CAPS	3" DIA.		12
CALV. WASHERS	2 1/2" DIA.		12

BILL OF MATERIALS			
ITEM	SIZE	LENGTH	NO. REQ.
A - ANGLE IRON	3" x 3" x 1/4"	7'-0"	4
B - ANGLE IRON	2" x 2" x 1/4"	7'-0"	4
C - ANGLE IRON	2" x 2" x 1/4"	4'-0"	4
ANCHOR BOLT AS-1 WITH NUTS	1/2" DIA.	0'-0"	4
STEEL BARS - PLAIN	NO. 4	9'-0"	1
STEEL BARS - PLAIN	NO. 4	7'-0"	4
STEEL BARS - PLAIN	NO. 4	11'-0"	10

\* SEE DETAIL OF BASE  
WELD ALL POINTS OF CONTACT BETWEEN ANGLE IRON



SECTION-H




SECTION-B




SECTION-F




SECTION-E




ISOMETRIC VIEW



ISOMETRIC VIEW OF INSIDE OF RISER STUB



SECTION I-I



SECTION J-J

DETAILS OF LOW STAGE TRASH RACK

SCALE 1/4" = 1'-0" (ENC. H, I)

**"AS BUILT"**

STRUCTURAL DIMENSIONS & TRASH RACK DETAILS  
FLOOD PREVENTION BASIN  
FLOOD PREVENTION PROJECT  
FLOOD DETENTION SITE, NC-2 P17  
KEYSER, WEST, VIRGINIA 7-1-77

U. S. DEPARTMENT OF AGRICULTURE  
SOIL CONSERVATION SERVICE

Designed by E. DURLINSKY - G.L.M.	Date DEC. 77	Checked by E.T. BROWNING, JR.	Date JAN. 78
Drawn by E.T. BROWNING, JR.	Date JAN. 78	Checked by M. J. CROSSLAND	Date FEB. 78
Drawing No. WP-499-P		Sheet No. 4 of 8	

FOR DETAILS OF 12" GATE VALVE SEE SHEET 8



---

---

Appendix B  
Site Inspection Checklist and Photos

---

---

**WATERSHED** New Creek  
**COUNTY** Mineral  
**OWNER** \_\_\_\_\_  
**ADDRESS** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

**SITE NUMBER** 17  
**NID #** 05706      **HAZARD CLASS** C  
**PURPOSE OF DAM** Flood Control  
**INSPECTION DATE** 9/2/2010  
**WEATHER** Sunny, 95° F

ITEM	Y	N	N/A	REMARKS
<b>1. General Conditions</b>				
a. Alterations to dam?		X		
b. Grass cover adequate?		X		Bare earth tire ruts on crest, upstream and downstream slopes need to be mowed
c. Settlements, misalignments or cracks?	X			Downstream slope
d. Vehicle ruts or animal trails?	X			Bare earth tire ruts along crest of dam, down auxiliary spillway training dike, and on left, downstream face
e. Fencing adequate?		X		Gates missing
f. Recent high water marks?		X		elevation
g. Development in flood pool?		X		
h. Development in downstream floodplain?	X			Houses and farms
i. Development in upstream watershed?	X			Recent subdivision just upstream of dam (1990's)
<b>2. Upstream Slope</b>				
a. Erosion?		X		
b. Trees?	X			Woody vegetation
c. Rodent holes?		X		
d. Cracks, settlements or bulges?		X		
e. Adequate and sound riprap?	X			
<b>3. Downstream Slope</b>				
a. Erosion?		X		
b. Trees?	X			Woody vegetation
c. Rodent holes?	X			Near toe of embankment and principal spillway conduit outlet
d. Cracks, settlements, & bulges?	X			Areas of large cobbles appear to be irregular possibly due to creep
e. Drains or wells flowing?			X	estimated gpm      No drains visible
f. Seepage or boils?	X			estimated gpm      Seep around cradle beneath principal spillway conduit visibly flowing
<b>4. Intake Structure</b> concrete <u>X</u> metal				water surface elevation
a. Spalling, cracking, & scaling?				None observed. Interior not accessed.
b. Exposed reinforcement?				None observed. Interior not accessed.
c. Corrosion present?	X			Low level trash rack and drawdown handwheel need to be painted
d. Manhole cover?	X			
e. Leakage?				estimated gpm      None observed. Interior not accessed.
f. Trash rack adequate?	X			
g. Inlet obstructed?	X			Minor debris surrounding lower inlet. Large branch lodged in riser structure.
h. Drawdown operative? closed ___ open <u>X</u>				Not accessed. Unknown.
i. Ladder intact?			X	
j. Pedestal securely fastened?				Not accessed. Unknown.
k. Floodgates operational?				Not accessed. Unknown.
l. Stem bent?		X		Visible portion not bent.
m. Stem guides operational?				Not accessed. Unknown.
n. Stem handwheel present?	X			
o. Do metal parts require painting?	X			Low level trash rack and drawdown handwheel
<b>5. Abutment Contacts</b>				
a. Erosion, cracks, or slides?		X		
b. Seepage?		X		
c. Gutters intact?	X			Trees encroaching on all gutters.
<b>6. Auxiliary Spillway</b>				
a. Obstructions?	X			Small, wooden fence in auxiliary spillway channel.
b. Erosion?		X		
c. Rodent holes?		X		
d. Low areas?		X		
e. Slips?		X		

ITEM	Y	N	N/A	REMARKS
<b>7. Conduit &amp; Outlet</b> concrete <input checked="" type="checkbox"/> metal				tailwater elevation/flow
a. Spalling, cracking, & scaling?	<input checked="" type="checkbox"/>			~4-foot-long fracture observed on the principal spillway conduit outlet.
b. Exposed reinforcement?				None observed. See Note 1.
c. Joints displaced or offset?				None observed. See Note 1.
d. Joint material lost?				None observed. See Note 1.
e. Leakage?				None observed. See Note 1.
f. Earth erosion?				None observed. See Note 1.
g. Conduit misaligned?				Not observed. See Note 1.
h. Outlet channel obstructed?	<input checked="" type="checkbox"/>			Thick vegetation around conduit outlet and plunge pool.
<b>8. Stilling Basin</b> Plunge Pool <input checked="" type="checkbox"/>				
a. Spalling, cracking, & scaling?			<input checked="" type="checkbox"/>	
b. Exposed reinforcement?			<input checked="" type="checkbox"/>	
c. Joints displaced or offset?			<input checked="" type="checkbox"/>	
d. Joint material lost?			<input checked="" type="checkbox"/>	
e. Joints leak?			<input checked="" type="checkbox"/>	
f. Rock adequate?	<input checked="" type="checkbox"/>			
g. Dissipater deteriorating?			<input checked="" type="checkbox"/>	
h. Dissipater clean of debris?			<input checked="" type="checkbox"/>	
i. Toe drains visible?			<input checked="" type="checkbox"/>	No drains visible
j. Toe drains flowing?			<input checked="" type="checkbox"/>	
k. Toe drain animal guards in place?			<input checked="" type="checkbox"/>	
<b>9. Reservoir</b>				
a. Buildings in floodpool?		<input checked="" type="checkbox"/>		
b. Slides or erosion on banks?		<input checked="" type="checkbox"/>		
c. Debris?		<input checked="" type="checkbox"/>		
d. Unsecured boats/docks?		<input checked="" type="checkbox"/>		
e. Sediment deposits?		<input checked="" type="checkbox"/>		
<b>10. Instruments</b>				
a. Structure instrumented?		<input checked="" type="checkbox"/>		
b. Monitoring performed?			<input checked="" type="checkbox"/>	
<b>11. Development</b>				
a. New development upstream of dam?		<input checked="" type="checkbox"/>		
b. New development downstream of dam?	<input checked="" type="checkbox"/>			Since dam was constructed.
c. EAP plan and mapping adequate?				To be determined by others.
<b>12. Hazard Classification Correct?</b>	<input checked="" type="checkbox"/>			


**REMARKS:**

- Upstream and downstream slopes are covered with patches of thick woody vegetation and need to be mowed.
- Bare earth tire ruts along crest of dam, on left side of upstream slope, and on auxiliary spillway training dike.
- Gates are needed to impede ATV traffic on crest and face of dam.
- Animal burrow observed near toe of dam.
- The areas of large cobbles on the downstream face appear to be very irregular possibly to due creep of the steep slope. They are also thickly overgrown with vegetation due to the inability to mow.
- Seep beneath cradle at the principal spillway conduit outlet is visibly flowing.
- Low level trash rack and drawdown handwheel need to be painted.
- Small, wooden fence could obstruct flow in auxiliary spillway channel.
- Thick vegetation surrounding plunge pool and principal spillway outlet conduit.
- Significant fracture and deterioration of concrete lining of principal spillway conduit outlet observed.

Note 1: The conduit and outlet were inspected from the downstream end. A comprehensive inspection of the conduit has not been performed as part of this inspection.

ENGINEER William Franz

DATE 11/19/10

SIGNATURE   
 Engineer

PROFESSIONAL ENGINEER SEAL

**GENERAL**



1. General overview of dam from right side of auxiliary spillway.



2. Principal spillway riser structure.

**GENERAL**



3. Upstream embankment slope.



4. Downstream embankment slope.

GENERAL



5. Outlet conduit.



6. Plunge pool.

## OBSERVED DEFICIENCIES



7. Bare earth tire ruts on dam crest, left side of upstream slope, and auxiliary spillway training dike.



8. Animal burrow near toe of downstream embankment.

**OBSERVED DEFICIENCIES**



9. Woody vegetation on upstream slope of dam embankment and auxiliary spillway entrance slope.



10. Woody vegetation on downstream embankment, especially in areas of large cobbles. Cobbled slope appears irregular due to overgrowth and possibly creep.

**OBSERVED DEFICIENCIES**



11. Plunge pool and outlet conduit are overgrown with vegetation.



12. Seep around cradle beneath principal spillway conduit visibly flowing.

**OBSERVED DEFICIENCIES**



13. Significant fracture (~4 feet long) of principal spillway conduit outlet.



14. Minor debris obstructing lower inlet of principal spillway. Large tree branch lodged in principal spillway riser structure.

**OBSERVED DEFICIENCIES**



15. Lower trash rack and drawdown gate stem and handwheel show signs of corrosion and need to be painted.



16. Small, wooden fence in auxiliary spillway channel.



---

---

Appendix C  
SITES Output

---

---



---

## SITES Output

New Creek Site 17 – ASW Crest Criteria

---

# New Creek Site 17 – ASW Crest Criteria

1\*\*\*\*\*  
 SITES XEQ 02/10/2011 WATER RESOURCE SITE ANALYSIS COMPUTER PROGRAM  
 VER 2005.1.04 (USER MANUAL - DATED DECEMBER 2005)  
 TIME 16:24:07

\*\*\*\*\* 80-80 LIST OF INPUT DATA \*\*\*\*\*

SITES	01/01/2005NC17	New Creek Site 17		1.696875	A1
SAVMOV	0 101				
SAVMOV	101 1				1
STRUCTURE	17				
	1090			0	
	1095			3.4	
	1100			12.4	
	1105			28.25	
	1110			53.1	
	1115			88.55	
	1120			136	
	1125			195.65	
	1130			269.5	
	1135			360.35	
	1140			470.1	
	1145			602.85	
	1160			1100	
ENDTABLE					
WSDATA	2C 17 AC 72	1086	0.78	6.2	
BASEFLOW		0.95			
PDIRECT		5.82	8.45		
POOLDATA	ELEV		1104.12	1104.12	TC
PSINLET	ELEV	0.75	12	1128.4	1.18 1.18
PSDATA	1	280.33	24	0.013	1076.01
GRAPHICS	I				
GO,DESIGN	LN				
SAVMOV	2 101 1		17		
ENDJOB					

\*\*\*\*\*

\*\*\*\*\* MESSAGE - DRAINAGE AREA FROM WSDATA CONTROL BEING CONVERTED FROM  
 ACRES TO SQUARE MILES FOR COMPUTATION PURPOSES.

1SITES -----  
 XEQ 02/10/2011 New Creek Site 17 WSID= NC17  
 VER 2005.1.04 SUBW= 17  
 TIME 16:24:07 SITE = 17 PASS= 1 PART= 1

\*\*\*\*\* BASIC DATA \*\*\*\*\*  
 HUMID- SUBHUMID CLIMATE AREA DESIGN CLASS C

STORM DISTRIBUTION PSH..10 DAY NRCS DESIGN STORM (CHAPTER 21, NEH4 & TR-60).

STORM DISTRIBUTION USED FOR AUXILIARY SPILLWAY IS;  
 NRCS DESIGN STORM RAINFALL DISTRIBUTION (CHAPTER 21, NEH4 & TR-60).

PRECIP. - P-PS,1-DAY	P-PS,10-DAY	Q-SD	Q-FB
5.82	8.45	0.00	0.00
WSDATA - CN	DA-SM	TC/L	-/H QRF
72.00	1.70	0.78	0.00 6.20
SITEDATA- PERM POOL	CREST PS	FP SED	VALLEY FL 378?
0.00	1104.12	1104.12	0.00 NO
BASEFLOW	INITIAL EL	EXTRA VOL	SITE TYPE
0.95	0.00	0.00	DESIGN

## New Creek Site 17 – ASW Crest Criteria

PSDATA -	NO. COND	COND L	DIA/W	-/H	
	1.00	280.33	24.00	0.00	
	PS N	KE	WEIR L	TW EL	
	0.013	0.75	12.00	1076.01	
	2ND STG	ORF H	ORF L	START AUX.	
	1128.40	1.18	1.18	0.00	
ASCRESTS -	AUX.1	AUX.2	AUX.3	AUX.4	AUX.5
	0.00	0.00	0.00	0.00	0.00
AUX.DATA -	REF.NO.	RETARD. Ci	TIE STATION	INLET LENGTH	
	0	0.00	0.00	0	
AUX.DATA -	INLET N	SIDE SLOPE	EXIT N	EXIT SLOPE	ACTUAL AUX?
	0.000	0.00	0.000	0.000	NO
BTM WIDTH -	BW1	BW2	BW3	BW4	BW5
	0.00	0.00	0.00	0.00	0.00

1SITES -----

XEQ 02/10/2011	New Creek Site 17	WSID= NC17
VER 2005.1.04		SUBW= 17
TIME 16:24:07	SITE = 17	PASS= 1    PART= 2

CREST PS	1104.12 FT	25.5 ACFT	0.00 AC	0.0 CFS
SED ACCUM	1104.12 FT	25.5 ACFT	0.00 AC	0.0 CFS
BASEFLOW	1104.69 FT	27.3 ACFT	0.00 AC	1.6 CFS
2ND STAGE	1128.40 FT	245.9 ACFT	0.00 AC	32.6 CFS
START ELEV	1104.69 FT	27.3 ACFT	0.00 AC	1.6 CFS

NRCS-PSH RAINFALL	1-DAY =	5.82 IN	10-DAY =	8.45 IN	DA =	1.70 SM
RUNOFF	1-DAY =	2.85 IN	10-DAY =	2.98 IN		

CLIMATIC INDEX = 1.00    CN 10-DAY = 54.    CN 1-DAY = 72.  
 QRF = 10.52 CFS    1109.36 FEET,    GIVEN VALUE.  
 PEAK = 2665.3 CFS, AT 120.1 HRS.

ROUTED RESULT -	HYD TYPE	EMAX	VOL-MAX	AMAX	QMAX
	NRCS-PSH	1130.06 FT	270.6 ACFT	0.00 AC	80.9 CFS

PS STORAGE 245.1 ACFT, BETWEEN AUX. CREST AND SED. ACCUM ELEVATIONS.

DRAWDOWN (DDT) TEST	1111.51 FT	63.8 ACFT	15.77 CFS
CONTROL IS 0.150 DETENTION STORAGE			

TIME TO DDT TEST DISCHARGE IS 6.66 DAYS - DRAWDOWN CONTINUING.

TIME LIMIT = 10.00 DAYS; FLOW WAS 12.31 CFS, ELEV = 1109.59 FT

\*\*\*\*\*  
 RATING TABLE DEVELOPED, SITE = 17 :  
 WITH PS DEVELOPED BY PROGRAM AND NO AUX. DATA GIVEN.

RATING TABLE NUMBER	1				
ELEV.	Q-TOTAL	Q-PS	Q-AUX.	VOLUME	AREA
FEET	CFS	CFS	CFS	AC-FT	ACRE

## New Creek Site 17 – ASW Crest Criteria

1	1104.12	0.00	0.00	0.00	25.46	0.00
2	1104.35	0.40	0.40	0.00	26.19	0.00
3	1104.58	1.13	1.13	0.00	26.91	0.00
TRANSITION TO ORIFICE FLOW, ELEV = 1104.81 FT						
4	1104.81	2.08	2.08	0.00	27.64	0.00
5	1112.67	18.91	18.91	0.00	72.04	0.00
6	1120.54	26.65	26.65	0.00	142.39	0.00
7	1128.40	32.61	32.61	0.00	245.87	0.00
8	1128.79	41.96	41.96	0.00	251.64	0.00
9	1129.18	58.83	58.83	0.00	257.41	0.00
FULL CONDUIT FLOW, ELEV = 1129.57 FT						
10	1129.57	80.60	80.60	0.00	263.18	0.00
11	1139.71	87.95	87.95	0.00	463.84	0.00
12	1149.86	94.70	94.70	0.00	763.84	0.00
13	1160.00	100.99	100.99	0.00	1100.00	0.00

```

1SITES -----
XEQ 02/10/2011                New Creek Site 17                WSID= NC17
VER 2005.1.04                SUBW= 17
TIME 16:24:07                SITE = 17                PASS= 1                PART= 3
  
```

AUX. CREST      1130.06 FT      270.6 ACFT      0.00 AC      80.9 CFS

PS STORAGE      245.1 ACFT, BETWEEN AUX. CREST AND SED. ACCUM ELEVATIONS.

START ELEV      1109.59 FT      51.0 ACFT      0.00 AC      12.3 CFS

ELEVATION OF LOW POINT IS ZERO. NO CRITERIA CHECK MADE FOR  
STRUCTURE CLASSIFICATION.

\*\*\*\*\* MESSAGE - NO INPUT DATA GIVEN FOR AUXILIARY SPILLWAY CREST AND/OR  
BOTTOM WIDTH. NO AUXILIARY SPILLWAY ROUTINGS PERFORMED.

```

-----
Inflow Hyd 1 PSH-Peak =      80.87 CFS at 121.52 hrs., Location Point
HYDOUT 1      17
  
```

1SITES....JOB NO. 1 COMPLETE.

```

-----
NC17      New Creek Site 17
  
```

0 SUBWATERSHED(S) ANALYZED.

1 STRUCTURE(S) ANALYZED.

1 HYDROGRAPHS ROUTED AT LOWEST SITE.

0 TRIALS TO OBTAIN BOTTOM WIDTH FOR SPECIFIED STRESS OR VELOCITY.

\*\*\*\*\*





---

## SITES Output

New Creek Site 17 – Top of Dam (6-hr)

---

# New Creek Site 17 – Top of Dam (6-hr)

```

1*****
SITES XEQ 02/10/2011   WATER RESOURCE SITE ANALYSIS COMPUTER PROGRAM
VER 2005.1.04         (USER MANUAL - DATED DECEMBER 2005)
TIME 16:24:39
  
```

\*\*\*\*\* 80-80 LIST OF INPUT DATA \*\*\*\*\*

```

SITES      01/01/2005NC17      New Creek Site 17      1.696875  C2
SAVMOV     0      101
SAVMOV    101  1
STRUCTURE  17

                1090                0
                1095                3.4
                1100                12.4
                1105                28.25
                1110                53.1
                1115                88.55
                1120                136
                1125                195.65
                1130                269.5
                1135                360.35
                1140                470.1
                1145                602.85
                1160                1100

ENDTABLE
WSDATA    2C 17  AC 72      1086      0.78
BASEFLOW      0.95
PDIRECT                9.90      27.30
POOLDATA  ELEV      1104.12  1104.12  1104.12  1086      1074      TC
PSINLET  ELEV      0.75     12      1128.4   1.18     1.18
PSDATA   1      280.33   24      0.013   1076.01
ASSPRFL  41
          -81      1123.5  -56     1135.18 -10     1136.1
          10      1136.1   69     1134.92 181     1125.176

ENDTABLE
ASSURFACE 41      69      0.1
          -81     -56     0.02    0.5     1       1
          -56     -10     0.035   0.5     1       1
          -10     10      0.035   0.5     1       1
          10      69      0.035   0.5     1       1
          69      181     0.035   0.5     1       1

ENDTABLE
ASDATA    41                2.5                2
BTMWIDTH  FEET      200
GRAPHICS  I
GO,DESIGN HL                6                1104.12
SAVMOV    2      101  1      17
ENDJOB
  
```

\*\*\*\*\*

\*\*\*\*\* MESSAGE - DRAINAGE AREA FROM WSDATA CONTROL BEING CONVERTED FROM ACRES TO SQUARE MILES FOR COMPUTATION PURPOSES.

\*\*\*\*\* MESSAGE - AUXILIARY SPILLWAY CREST ELEVATION IS SET TO 1136.10 FROM THE ASSPRFL RECORDS.

```

1SITES -----
XEQ 02/10/2011      New Creek Site 17      WSID= NC17
VER 2005.1.04      SUBW= 17
TIME 16:24:39      SITE = 17      PASS= 1      PART= 1
  
```

```

***** BASIC DATA *****
HUMID- SUBHUMID CLIMATE AREA      DESIGN CLASS C
  
```

# New Creek Site 17 – Top of Dam (6-hr)

STORM DISTRIBUTION USED FOR AUXILIARY SPILLWAY IS;  
NRCS DESIGN STORM RAINFALL DISTRIBUTION (CHAPTER 21, NEH4 & TR-60).

PRECIP. - Q-PS,1-DAY	Q-PS,10-DAY	P-SD	P-FB		
0.00	0.00	9.90	27.30		
WSDATA - CN	DA-SM	TC/L	-/H	QRF	
72.00	1.70	0.78	0.00	0.00	
SITEDATA- PERM POOL	CREST PS	FP SED	VALLEY FL	378?	
1104.12	1104.12	1104.12	1074.00	NO	
BASEFLOW	INITIAL EL	EXTRA VOL	SITE TYPE		
0.95	0.00	0.00	DESIGN		
PSDATA - NO. COND	COND L	DIA/W	-/H		
1.00	280.33	24.00	0.00		
PS N	KE	WEIR L	TW EL		
0.013	0.75	12.00	1076.01		
2ND STG	ORF H	ORF L	START AUX.		
1128.40	1.18	1.18	1104.12		
ASCRESTS - AUX.1	AUX.2	AUX.3	AUX.4	AUX.5	
1136.10	0.00	0.00	0.00	0.00	
AUX.DATA - REF.NO.	RETARD. Ci	TIE STATION	INLET LENGTH		
41	0.00	10.00	0		
AUX.DATA - INLET N	SIDE SLOPE	EXIT N	EXIT SLOPE	ACTUAL AUX?	
0.035	2.50	0.035	0.020	NO	
BTM WIDTH - BW1	BW2	BW3	BW4	BW5	
ft 200.00	0.00	0.00	0.00	0.00	

AUXILIARY SPILLWAY RATING DEVELOPED USING WSPVRT.

```
1SITES -----
XEQ 02/10/2011           New Creek Site 17           WSID= NC17
VER 2005.1.04                                SUBW= 17
TIME 16:24:39           SITE = 17           PASS= 1           PART= 2
```

PERM POOL	1104.12 FT	25.5 ACFT	0.00 AC	0.0 CFS
CREST PS	1104.12 FT	25.5 ACFT	0.00 AC	0.0 CFS
SED ACCUM	1104.12 FT	25.5 ACFT	0.00 AC	0.0 CFS
BASEFLOW	1104.69 FT	27.3 ACFT	0.00 AC	1.6 CFS
2ND STAGE	1128.40 FT	245.9 ACFT	0.00 AC	32.6 CFS
START ELEV	1104.69 FT	27.3 ACFT	0.00 AC	1.6 CFS

\*\*\*\*\*  
RATING TABLE DEVELOPED, SITE = 17 :  
BY PROGRAM FOR PS AND AUX. SPILLWAYS  
AUX. RATING USED WSPVRT METHOD.

RATING TABLE NUMBER 1						
	ELEV.	Q-TOTAL	Q-PS	Q-AUX.	VOLUME	AREA
	FEET	CFS	CFS	CFS	AC-FT	ACRE
1	1104.12	0.00	0.00	0.00	25.46	0.00
2	1104.35	0.40	0.40	0.00	26.19	0.00
3	1104.58	1.13	1.13	0.00	26.91	0.00

## New Creek Site 17 – Top of Dam (6-hr)

TRANSITION TO ORIFICE FLOW, ELEV = 1104.81 FT						
4	1104.81	2.08	2.08	0.00	27.64	0.00
5	1112.67	18.91	18.91	0.00	72.04	0.00
6	1120.54	26.65	26.65	0.00	142.39	0.00
7	1128.40	32.61	32.61	0.00	245.87	0.00
8	1128.79	41.96	41.96	0.00	251.64	0.00
9	1129.18	58.83	58.83	0.00	257.41	0.00
FULL CONDUIT FLOW, ELEV = 1129.57 FT						
10	1129.57	80.60	80.60	0.00	263.18	0.00
11	1139.71	87.95	87.95	0.00	463.84	0.00
12	1149.86	94.70	94.70	0.00	763.84	0.00
13	1160.00	100.99	100.99	0.00	1100.00	0.00

```

1SITES -----
XEQ 02/10/2011                New Creek Site 17                WSID= NC17
VER 2005.1.04                                SUBW= 17
TIME 16:24:39                SITE = 17                PASS= 1                PART= 3
    
```

```

AUX. CREST      1136.10 FT      384.5 ACFT      0.00 AC      85.0 CFS

    PS STORAGE      359.0 ACFT, BETWEEN AUX. CREST AND SED. ACCUM ELEVATIONS.

START ELEV      1104.69 FT      27.3 ACFT      0.00 AC      1.6 CFS

EFFECTIVE HEIGHT(H)= 50.1 FEET, PRODUCT= 19263. (H * STORAGE AT CREST AUX.).

INPUT DESIGN CLASS = C
    
```

```

NRCS-SDH      D= 6.00 HR      P= 9.90 IN      Q= 6.40 IN      DA= 1.70 SM
               TC= 0.78 HR      CN= 72.00      VOL= 579.8 ACFT

    PEAK =      4092.3 CFS, AT 2.8 HRS.

NRCS-FBH      D= 6.00 HR      P= 27.30 IN     Q= 23.13 IN     DA= 1.70 SM
               TC= 0.78 HR      CN= 72.00      VOL= 2094.4 ACFT

    PEAK =      15062.4 CFS, AT 2.8 HRS.
    
```

```

*****
RATING TABLE DEVELOPED, SITE = 17 :
BY PROGRAM FOR PS AND AUX. SPILLWAYS
AUX. RATING USED WSPVRT METHOD.
    
```

RATING TABLE NUMBER 2						
	ELEV.	Q-TOTAL	Q-PS	Q-AUX.	VOLUME	AREA
	FEET	CFS	CFS	CFS	AC-FT	ACRE
1	1104.12	0.00	0.00	0.00	25.46	0.00
2	1104.35	0.40	0.40	0.00	26.19	0.00
3	1104.58	1.13	1.13	0.00	26.91	0.00
TRANSITION TO ORIFICE FLOW, ELEV = 1104.81 FT						
4	1104.81	2.08	2.08	0.00	27.64	0.00
5	1112.67	18.91	18.91	0.00	72.04	0.00
6	1120.54	26.65	26.65	0.00	142.39	0.00
7	1128.40	32.61	32.61	0.00	245.87	0.00
8	1128.79	41.96	41.96	0.00	251.64	0.00
9	1129.18	58.83	58.83	0.00	257.41	0.00
FULL CONDUIT FLOW, ELEV = 1129.57 FT						
10	1129.57	80.60	80.60	0.00	263.18	0.00
11	1131.75	82.27	82.27	0.00	301.26	0.00
12	1133.92	83.86	83.86	0.00	340.80	0.00
13	1136.10	85.42	85.42	0.00	384.50	0.00
14	1137.29	709.57	86.27	623.30	410.72	0.00
15	1138.49	2019.83	87.11	1932.73	436.96	0.00
16	1140.64	5679.57	88.59	5590.98	487.12	0.00
17	1143.27	11787.01	90.38	11696.64	556.92	0.00
18	1148.05	27540.17	93.53	27446.64	703.94	0.00

## New Creek Site 17 – Top of Dam (6-hr)

```

19 1154.03 52839.61    97.33 52742.27    901.97    0.00
20 1160.00 85026.20    100.99 84925.21    1100.00    0.00
*****

```

SUMMARY OF AUXILIARY SPILLWAY SURFACE CONDITIONS USED IN COMPUTATIONS BY REACH

REACH	FROM STA (ft)	TO STA (ft)	SLOPE (%)	RETARDANCE CURVE INDEX@	VEGETAL COVER FACTOR	MAINT. CODE	ROOTING DEPTH (ft)	REACH LOCATION *
1	-81.	-56.	-46.7	0.020	**	**	**	INLET
2	-56.	-10.	-2.0	0.035	**	**	**	INLET
3	-10.	10.	0.0	0.035	**	**	**	CREST
4	10.	69.	2.0	0.035	0.50	1	1.0	EXIT !
5	69.	181.	8.7	0.035	0.50	1	1.0	exit

@ The program interprets retardance curve index entries of less than 1 as Manning's n values.

\* Upper case indicates a reach of constructed spillway channel.

\*\* The program does not use vegetal cover factor, maintenance code, and rooting depth for inlet and crest reaches in computations.

! Reach 4 used in computing exit channel velocities.

\*\*\*\*\*

ROUTED RESULTS	BTM WIDTH FT	MAX ELEV FT	VOL-MAX ACFT	AREA-MAX AC	AUX.-HP FT	VOL-AUX. ACFT
NRCS-SDH	200.0	1137.60	417.5	0.0	1.50	33.0

PEAK - CFS DISCHARGE = Q-PS 86. Q-AUX. 960. Q-TOT. 1047.

	CRITICAL DEPTH FT	CRITICAL VELOCITY FT/SEC	CRITICAL SLOPE-Sc FT/FT	25% OF Q Sc FT/FT
AUXILIARY SPILLWAY ---	0.89	5.33	0.019	0.025

AUXILIARY SPILLWAY DURATION FLOW = 4.1 HOURS

EXIT CHANNEL FLOW SUPERCRITICAL: MAX VELOCITY= 5.4 FT/SEC  
EXIT SLOPE = 0.020 FT/FT  
FLOW DEPTH = 0.9 FT

\*\*\*\*\*

EROSIONALLY EFFECTIVE STRESS FOR STABILITY ANALYSIS OF AUX. EXIT CHANNEL  
(Refer to Ag. Handbook 667, Chapt. 3, for allowable stresses.)

Aux. Spillway Discharge = 960. cfs; Bottom Width = 200. ft

REACH NO.	FROM STA	TO STA	SLOPE %	MANNING`S n	VELOCITY ft/s	TOTAL STRESS lb/ft^2	EFFECTIVE STRESS lb/ft^2
4	10.	69.	2.00	0.035	5.44	1.09	0.136

\*\*\*\*\*

ROUTED RESULTS	BTM WIDTH FT	MAX ELEV FT	VOL-MAX ACFT	AREA-MAX AC	AUX.-HP FT	VOL-AUX. ACFT
NRCS-FBH	200.0	1143.91	574.0	0.0	7.81	189.5

PEAK - CFS DISCHARGE = Q-PS 91. Q-AUX. 13527. Q-TOT. 13618.

	CRITICAL DEPTH FT	CRITICAL VELOCITY FT/SEC	CRITICAL SLOPE-Sc FT/FT	25% OF Q Sc FT/FT
AUXILIARY SPILLWAY ---	5.11	12.45	0.011	0.014

AUXILIARY SPILLWAY DURATION FLOW = 5.7 HOURS  
ATTACK, OE/B = 8.5 ACFT/FT

EXIT CHANNEL FLOW SUPERCRITICAL: MAX VELOCITY= 15.2 FT/SEC  
EXIT SLOPE = 0.020 FT/FT

# New Creek Site 17 – Top of Dam (6-hr)

FLOW DEPTH = 4.2 FT

Inflow Hyd 1 SDH-Peak = 1046.66 CFS at 4.58 hrs., Location Point  
 Inflow Hyd 1 FBH-Peak = 13617.71 CFS at 2.96 hrs., Location Point  
 HYDOUT 1 17

1SITES....JOB NO. 1 COMPLETE.

-----  
 NC17 New Creek Site 17  
 0 SUBWATERSHED(S) ANALYZED.  
 1 STRUCTURE(S) ANALYZED.  
 2 HYDROGRAPHS ROUTED AT LOWEST SITE.  
 0 TRIALS TO OBTAIN BOTTOM WIDTH FOR SPECIFIED STRESS OR VELOCITY.  
 \*\*\*\*\*

SITES.....COMPUTATIONS COMPLETE

1 SUMMARY TABLE 1 SITES VERSION 2005.1.04  
 ----- DATED 01/01/2005

WATERSHED ID		RUN DATE				RUN TIME			
-----		-----				-----			
NC17		02/10/2011				16:24:39			
>>>	SITE ID	SUBWS ID	SUBWS DA (SQ MI)	CURVE NO.	TC (HRS)	TOTAL DA (SQ MI)	TYPE DESIGN	STRUC CLASS	<<<
	-----	-----	-----	-----	-----	-----	-----	-----	
	17	17	1.70	72.	0.78	1.70	TR60	C	
PASS NO.	DIA./ WIDTH (IN/FT)	AUX.CREST ELEV (FT)	BTM. WIDTH (FT)	MAX. HP (FT)	MAX. ELEV (FT)	EMB. VOL. (CY)	INTEGR.* DIST. (FT)	EXIT* VEL. (FT/SEC)	TYPE HYD
-----	-----	-----	-----	-----	-----	-----	-----	-----	-----
1	24.0	1136.1	200.0	7.8	1143.9	0.	0.	15.1	NRCS-FBH

\* INTEGRITY DIST. AND EXIT VEL. VALUES ARE BASED ON THE ROUTED HYDROGRAPH SHOWN UNDER TYPE HYD.

SITES.....SUMMARY TABLE 1 COMPLETED.

NRCS SITES VERSION 2005.1.04 ,01/01/2005  
 NC17 FILES

INPUT = W:\426\Active Jobs\52299 - WV NRCS 2010 Contract\05 Working\41 Dam Assessments\New Creek Site 17\NC17 SITES Model\NC17\NC\_Site17\_Estimating\_TOD\_Crest.D2C  
 OUTPUT = W:\426\Active Jobs\52299 - WV NRCS 2010 Contract\05 Working\41 Dam Assessments\New Creek Site 17\NC17 SITES Model\NC17\NC\_Site17\_Estimating\_TOD\_Crest.OUT  
 DATED 02/10/2011 16:24:39

## New Creek Site 17 – Top of Dam (6-hr)

### GRAPHICS FILES GENERATED

OPTION "L" = W:\426\Active Jobs\52299 - WV NRCS 2010 Contract\05 Working\41 Dam Assessments\New Creek Site 17\NC17 SITES Model\NC17\NC\_Site17\_Estimating\_TOD\_Crest.DRG  
DATED 02/10/2011 16:24:39

OPTION "P" = W:\426\Active Jobs\52299 - WV NRCS 2010 Contract\05 Working\41 Dam Assessments\New Creek Site 17\NC17 SITES Model\NC17\NC\_Site17\_Estimating\_TOD\_Crest.DHY  
DATED 02/10/2011 16:24:39

OPTION "E" = W:\426\Active Jobs\52299 - WV NRCS 2010 Contract\05 Working\41 Dam Assessments\New Creek Site 17\NC17 SITES Model\NC17\NC\_Site17\_Estimating\_TOD\_Crest.DEM  
DATED 02/10/2011 16:24:39



---

## SITES Output

New Creek Site 17 – Top of Dam (24-hr)

---

# New Creek Site 17 – Top of Dam (24-hr)

```

1*****
SITES XEQ 02/10/2011  WATER RESOURCE SITE ANALYSIS COMPUTER PROGRAM
VER 2005.1.04          (USER MANUAL - DATED DECEMBER 2005)
TIME 16:25:30
  
```

\*\*\*\*\* 80-80 LIST OF INPUT DATA \*\*\*\*\*

```

SITES      01/01/2005NC17      New Creek Site 17      1.696875  C2
SAVMOV     0      101
SAVMOV     101  1
STRUCTURE  17

          1090          0
          1095          3.4
          1100          12.4
          1105          28.25
          1110          53.1
          1115          88.55
          1120          136
          1125          195.65
          1130          269.5
          1135          360.35
          1140          470.1
          1145          602.85
          1160          1100

ENDTABLE
WSDATA     2C 17  AC 72      1086      0.78
BASEFLOW   0.95
RAINTABLE  17      24
          0      0.008      0.0162      0.0246      0.0333
          0.0425      0.0524      0.063      0.0743      0.0863
          0.099      0.1124      0.1265      0.142      0.1595
          0.18      0.205      0.255      0.345      0.437
          0.53      0.603      0.633      0.66      0.684
          0.705      0.724      0.742      0.759      0.775
          0.79      0.8043      0.818      0.8312      0.8439
          0.8561      0.8678      0.879      0.8898      0.9002
          0.9103      0.9201      0.9297      0.9391      0.9483
          0.9573      0.9661      0.9747      0.9832      0.9916
          1

ENDTABLE
PDIRECT
POOLDATA   ELEV      1104.12      1104.12      1104.12      1086      1074      TC
PSINLET    ELEV      0.75      12      1128.40      1.18      1.18
PSDATA     1      280.33      24
ASSPRFL    41
          -81      1123.5      -56      1135.18      -10      1136.1
          10      1136.1      69      1134.92      181      1125.176

ENDTABLE
ASSURFACE  41      69      0.1
          -81      -56      0.02      0.5      1      1
          -56      -10      0.035      0.5      1      1
          -10      10      0.035      0.5      1      1
          10      69      0.035      0.5      1      1
          69      181      0.035      0.5      1      1

ENDTABLE
ASDATA     41
BTMWIDTH   FEET      200
GRAPHICS   I
GO,DESIGN  HL      17      24      1104.12
SAVMOV     2      101  1
ENDJOB
  
```

\*\*\*\*\*

\*\*\*\*\* MESSAGE - DRAINAGE AREA FROM WSDATA CONTROL BEING CONVERTED FROM ACRES TO SQUARE MILES FOR COMPUTATION PURPOSES.

## New Creek Site 17 – Top of Dam (24-hr)

\*\*\*\*\* MESSAGE - AUXILIARY SPILLWAY CREST ELEVATION IS SET TO 1136.10  
FROM THE ASSPRFL RECORDS.

```

LSITES -----
XEQ 02/10/2011                 New Creek Site 17                 WSID= NC17
VER 2005.1.04                                SUBW= 17
TIME 16:25:30                SITE = 17                PASS= 1        PART= 1
    
```

```

***** BASIC DATA *****
HUMID- SUBHUMID CLIMATE AREA                DESIGN CLASS C
    
```

STORM DISTRIBUTION AUX. -

PRECIP. - Q-PS,1-DAY	Q-PS,10-DAY	P-SD	P-FB	
0.00	0.00	13.40	34.80	
WSDATA - CN	DA-SM	TC/L	-/H	QRF
72.00	1.70	0.78	0.00	0.00
SITEDATA- PERM POOL	CREST PS	FP SED	VALLEY FL	378?
1104.12	1104.12	1104.12	1074.00	NO
BASEFLOW	INITIAL EL	EXTRA VOL	SITE TYPE	
0.95	0.00	0.00	DESIGN	
PSDATA - NO. COND	COND L	DIA/W	-/H	
1.00	280.33	24.00	0.00	
PS N	KE	WEIR L	TW EL	
0.013	0.75	12.00	1076.01	
2ND STG	ORF H	ORF L	START AUX.	
1128.40	1.18	1.18	1104.12	
ASCRESTS - AUX.1	AUX.2	AUX.3	AUX.4	AUX.5
1136.10	0.00	0.00	0.00	0.00
AUX.DATA - REF.NO.	RETARD. Ci	TIE STATION	INLET LENGTH	
41	0.00	10.00	0	
AUX.DATA - INLET N	SIDE SLOPE	EXIT N	EXIT SLOPE	ACTUAL AUX?
0.035	2.50	0.035	0.020	NO
BTM WIDTH - BW1	BW2	BW3	BW4	BW5
ft 200.00	0.00	0.00	0.00	0.00

AUXILIARY SPILLWAY RATING DEVELOPED USING WSPVRT.

```

LSITES -----
XEQ 02/10/2011                 New Creek Site 17                 WSID= NC17
VER 2005.1.04                                SUBW= 17
TIME 16:25:30                SITE = 17                PASS= 1        PART= 2
    
```

PERM POOL	1104.12 FT	25.5 ACFT	0.00 AC	0.0 CFS
CREST PS	1104.12 FT	25.5 ACFT	0.00 AC	0.0 CFS
SED ACCUM	1104.12 FT	25.5 ACFT	0.00 AC	0.0 CFS
BASEFLOW	1104.69 FT	27.3 ACFT	0.00 AC	1.6 CFS
2ND STAGE	1128.40 FT	245.9 ACFT	0.00 AC	32.6 CFS
START ELEV	1104.69 FT	27.3 ACFT	0.00 AC	1.6 CFS



## New Creek Site 17 – Top of Dam (24-hr)

8	1128.79	41.96	41.96	0.00	251.64	0.00
9	1129.18	58.83	58.83	0.00	257.41	0.00
FULL CONDUIT FLOW, ELEV = 1129.57 FT						
10	1129.57	80.60	80.60	0.00	263.18	0.00
11	1131.75	82.27	82.27	0.00	301.26	0.00
12	1133.92	83.86	83.86	0.00	340.80	0.00
13	1136.10	85.42	85.42	0.00	384.50	0.00
14	1137.29	709.57	86.27	623.30	410.72	0.00
15	1138.49	2019.83	87.11	1932.73	436.96	0.00
16	1140.64	5679.57	88.59	5590.98	487.12	0.00
17	1143.27	11787.01	90.38	11696.64	556.92	0.00
18	1148.05	27540.17	93.53	27446.64	703.94	0.00
19	1154.03	52839.61	97.33	52742.27	901.97	0.00
20	1160.00	85026.20	100.99	84925.21	1100.00	0.00

\*\*\*\*\*

SUMMARY OF AUXILIARY SPILLWAY SURFACE CONDITIONS USED IN COMPUTATIONS BY REACH

REACH	FROM STA (ft)	TO STA (ft)	SLOPE (%)	RETARDANCE CURVE INDEX@	VEGETAL COVER FACTOR	MAINT. CODE	ROOTING DEPTH (ft)	REACH LOCATION *
1	-81.	-56.	-46.7	0.020	**	**	**	INLET
2	-56.	-10.	-2.0	0.035	**	**	**	INLET
3	-10.	10.	0.0	0.035	**	**	**	CREST
4	10.	69.	2.0	0.035	0.50	1	1.0	EXIT !
5	69.	181.	8.7	0.035	0.50	1	1.0	exit

@ The program interprets retardance curve index entries of less than 1 as Manning's n values.

\* Upper case indicates a reach of constructed spillway channel.

\*\* The program does not use vegetal cover factor, maintenance code, and rooting depth for inlet and crest reaches in computations.

! Reach 4 used in computing exit channel velocities.

\*\*\*\*\*

ROUTED RESULTS	BTM WIDTH FT	MAX ELEV FT	VOL-MAX ACFT	AREA-MAX AC	AUX.-HP FT	VOL-AUX. ACFT
NRCS-SDH	200.0	1137.66	418.6	0.0	1.56	34.2

PEAK - CFS                    Q-PS            Q-AUX.            Q-TOT.  
DISCHARGE =                  87.            1019.            1105.

CRITICAL    CRITICAL    CRITICAL    25% OF Q  
DEPTH      VELOCITY    SLOPE-Sc    Sc  
AUXILIARY    FT            FT/SEC      FT/FT      FT/FT  
SPILLWAY ---    0.93        5.43        0.018      0.025

AUXILIARY SPILLWAY DURATION FLOW =            14.9 HOURS

EXIT CHANNEL FLOW SUPERCRITICAL: MAX VELOCITY=    5.6 FT/SEC  
EXIT SLOPE      = 0.020 FT/FT  
FLOW DEPTH     = 0.9 FT

\*\*\*\*\*

EROSIONALLY EFFECTIVE STRESS FOR STABILITY ANALYSIS OF AUX. EXIT CHANNEL  
(Refer to Ag. Handbook 667, Chapt. 3, for allowable stresses.)

Aux. Spillway Discharge =    1019. cfs;    Bottom Width =    200. ft

REACH NO.	FROM STA	TO STA	SLOPE %	MANNING'S n	VELOCITY ft/s	TOTAL STRESS lb/ft^2	EFFECTIVE STRESS lb/ft^2
4	10.	69.	2.00	0.035	5.57	1.13	0.140

\*\*\*\*\*

ROUTED RESULTS	BTM WIDTH FT	MAX ELEV FT	VOL-MAX ACFT	AREA-MAX AC	AUX.-HP FT	VOL-AUX. ACFT
NRCS-FBH	200.0	1141.15	500.7	0.0	5.05	116.2

PEAK - CFS                    Q-PS            Q-AUX.            Q-TOT.

## New Creek Site 17 – Top of Dam (24-hr)

DISCHARGE = 89. 6780. 6869.

	CRITICAL DEPTH	CRITICAL VELOCITY	CRITICAL SLOPE-Sc	25% OF Q Sc
AUXILIARY SPILLWAY ---	FT	FT/SEC	FT/FT	FT/FT
	3.25	10.03	0.012	0.017

AUXILIARY SPILLWAY DURATION FLOW = 17.6 HOURS  
 ATTACK, OE/B = 11.3 ACFT/FT

EXIT CHANNEL FLOW SUPERCRITICAL: MAX VELOCITY= 11.7 FT/SEC  
 EXIT SLOPE = 0.020 FT/FT  
 FLOW DEPTH = 2.8 FT

Inflow Hyd 1 SDH-Peak = 1105.37 CFS at 10.83 hrs., Location Point  
 Inflow Hyd 1 FBH-Peak = 6868.85 CFS at 9.84 hrs., Location Point  
 HYDOUT 1 17

1SITES....JOB NO. 1 COMPLETE.

-----

NC17 New Creek Site 17

0 SUBWATERSHED(S) ANALYZED.  
 1 STRUCTURE(S) ANALYZED.  
 2 HYDROGRAPHS ROUTED AT LOWEST SITE.  
 0 TRIALS TO OBTAIN BOTTOM WIDTH FOR SPECIFIED STRESS OR VELOCITY.

\*\*\*\*\*

SITES....COMPUTATIONS COMPLETE

1 SUMMARY TABLE 1 SITES VERSION 2005.1.04  
 ----- DATED 01/01/2005

WATERSHED ID									RUN TIME
-----									-----
NC17									16:25:30
>>>	SITE ID	SUBWS ID	SUBWS DA (SQ MI)	CURVE NO.	TC (HRS)	TOTAL DA (SQ MI)	TYPE DESIGN	STRUC CLASS	<<<
	-----	-----	-----	-----	-----	-----	-----	-----	
	17	17	1.70	72.	0.78	1.70	TR60	C	
PASS NO.	DIA./ WIDTH (IN/FT)	AUX. CREST ELEV (FT)	BTM. WIDTH (FT)	MAX. HP (FT)	MAX. ELEV (FT)	EMB. VOL. (CY)	INTEGR.* DIST. (FT)	EXIT* VEL. (FT/SEC)	TYPE HYD
-----	-----	-----	-----	-----	-----	-----	-----	-----	-----
1	24.0	1136.1	200.0	5.1	1141.2	0.	0.	11.7	NRCS-FBH

\* INTEGRITY DIST. AND EXIT VEL. VALUES ARE BASED ON THE ROUTED HYDROGRAPH SHOWN UNDER TYPE HYD.

## New Creek Site 17 – Top of Dam (24-hr)

SITES.....SUMMARY TABLE 1 COMPLETED.

NRCS SITES VERSION 2005.1.04 ,01/01/2005  
NC17 FILES

INPUT = W:\426\Active Jobs\52299 - WV NRCS 2010 Contract\05 Working\41 Dam  
Assessments\New Creek Site 17\NC17 SITES  
Model\NC17\NC\_Site17\_Estimating\_TOD\_Crest\_24Hr.D2C  
OUTPUT = W:\426\Active Jobs\52299 - WV NRCS 2010 Contract\05 Working\41 Dam  
Assessments\New Creek Site 17\NC17 SITES  
Model\NC17\NC\_Site17\_Estimating\_TOD\_Crest\_24Hr.OUT  
DATED 02/10/2011 16:25:30

GRAPHICS FILES GENERATED

OPTION "L" = W:\426\Active Jobs\52299 - WV NRCS 2010 Contract\05 Working\41 Dam  
Assessments\New Creek Site 17\NC17 SITES  
Model\NC17\NC\_Site17\_Estimating\_TOD\_Crest\_24Hr.DRG DATED 02/10/2011 16:25:30

OPTION "P" = W:\426\Active Jobs\52299 - WV NRCS 2010 Contract\05 Working\41 Dam  
Assessments\New Creek Site 17\NC17 SITES  
Model\NC17\NC\_Site17\_Estimating\_TOD\_Crest\_24Hr.DHY DATED 02/10/2011 16:25:30

OPTION "E" = W:\426\Active Jobs\52299 - WV NRCS 2010 Contract\05 Working\41 Dam  
Assessments\New Creek Site 17\NC17 SITES  
Model\NC17\NC\_Site17\_Estimating\_TOD\_Crest\_24Hr.DEM DATED 02/10/2011 16:25:30



---

## SITES Output

New Creek Site 17 - ASW Integrity (6-hr)

---

# New Creek Site 17 – ASW Integrity (6-hr)

```

1*****
SITES XEQ 02/10/2011  WATER RESOURCE SITE ANALYSIS COMPUTER PROGRAM
VER 2005.1.04          (USER MANUAL - DATED DECEMBER 2005)
TIME 16:22:53
  
```

\*\*\*\*\* 80-80 LIST OF INPUT DATA \*\*\*\*\*

```

SITES      01/01/2005NC17      New Creek Site 17      1.696875  C2
SAVMOV     0      101
SAVMOV     101  1
STRUCTURE  17

          1090          0
          1095          3.4
          1100          12.4
          1105          28.25
          1110          53.1
          1115          88.55
          1120          136
          1125          195.65
          1130          269.5
          1135          360.35
          1140          470.1
          1145          602.85
          1160          1100

ENDTABLE
WSDATA     2C 17  AC 72      1086      0.78
BASEFLOW   0.95
PDIRECT                    9.90      27.30
POOLDATA   ELEV      1104.12  1104.12  1104.12  1086      1074      TC
PSINLET    ELEV      0.75     12      1128.4   1.18     1.18
PSDATA     1      280.33     24      0.013    1076.01
ASSURFACE  41      139      0.1
          0      25      0.02     0.5      1      1
          25     139     0.035    0.5      1      1
          139    891     0.035    0.5      1      1

ENDTABLE
ASDATA     41                    2.5                    1
BTMWIDTH   FEET      200
ASMATERIAL
          1      12      0.004    28      125      0.37
          2      0      0.5      0      110      2

ENDTABLE
ASCOORD    1      Soil      Y
          0      1130     25      1135     63      1136.1
          83     1136.1   139     1135     207     1130
          314.00  1120     444.60  1115     539.00  1110
          626.00  1105     668.00  1100     792.00  1085
          835.00  1080     891.00  1070

ENDTABLE
ASCOORD    2      Shale
          0      1125     139     1125     207     1120
          314     1100     626     1085     891     1060

ENDTABLE
GRAPHICS   I
GO,DESIGN  L                    6                    1104.12
SAVMOV     2      101  1                    17
ENDJOB
  
```

\*\*\*\*\*

\*\*\*\*\* MESSAGE - DRAINAGE AREA FROM WSDATA CONTROL BEING CONVERTED FROM ACRES TO SQUARE MILES FOR COMPUTATION PURPOSES.

\*\*\*\*\* MESSAGE - DEFAULT TOPSOIL FILL MATERIAL PARAMETERS USED.

\*\*\*\*\* WARNING - HEADCUT ERODIBILITY INDEX OF 2.0 (MATERIAL 2) APPEARS INCONSISTENT WITH DENSITY OF 110.0.

## New Creek Site 17 – ASW Integrity (6-hr)

\*\*\*\*\* MESSAGE - AUXILIARY SPILLWAY CREST ELEVATION IS SET TO 1136.10  
FROM THE ASCOORD RECORDS.

```

1SITES -----
XEQ 02/10/2011          New Creek Site 17          WSID= NC17
VER 2005.1.04          SUBW= 17
TIME 16:22:53          SITE = 17          PASS= 1          PART= 1
  
```

```

***** MATERIAL PROPERTIES *****
          DRY          PERCENT          DETACH.          REP.
MATERIAL          PI          DENSITY          Kh          CLAY          RATE          DIAMETER
          lbs/CuFt          (Ft/H)/(lb/SqFt)          inches
Soil          12.          125.          0.37          28.0          --          0.00400
Shale          0.          110.          2.00          0.0          --          0.50000
TS_FILL          0.          100.          0.05          0.0          --          0.05000
GEN_FILL          12.          125.          0.37          28.0          --          0.00400
  
```

```

***** BASIC DATA *****
HUMID- SUBHUMID CLIMATE AREA          DESIGN CLASS C
  
```

STORM DISTRIBUTION USED FOR AUXILIARY SPILLWAY IS;  
NRCS DESIGN STORM RAINFALL DISTRIBUTION (CHAPTER 21, NEH4 & TR-60).

```

PRECIP. - Q-PS,1-DAY          Q-PS,10-DAY          P-SD          P-FB
          0.00          0.00          9.90          27.30

WSDATA -          CN          DA-SM          TC/L          -/H          QRF
          72.00          1.70          0.78          0.00          0.00

SITEDATA- PERM POOL          CREST PS          FP SED          VALLEY FL          378?
          1104.12          1104.12          1104.12          1074.00          NO

          BASEFLOW          INITIAL EL          EXTRA VOL          SITE TYPE
          0.95          0.00          0.00          DESIGN

PSDATA - NO. COND          COND L          DIA/W          -/H
          1.00          280.33          24.00          0.00

          PS N          KE          WEIR L          TW EL
          0.013          0.75          12.00          1076.01

          2ND STG          ORF H          ORF L          START AUX.
          1128.40          1.18          1.18          1104.12

ASCRESTS - AUX.1          AUX.2          AUX.3          AUX.4          AUX.5
          1136.10          0.00          0.00          0.00          0.00

AUX.DATA - REF.NO.          RETARD. Ci          TIE STATION          INLET LENGTH
          41          0.00          83.00          0

AUX.DATA - INLET N          SIDE SLOPE          EXIT N          EXIT SLOPE          ACTUAL AUX?
          0.035          2.50          0.035          0.020          YES

BTM WIDTH - BW1          BW2          BW3          BW4          BW5
ft          200.00          0.00          0.00          0.00          0.00
  
```

AUXILIARY SPILLWAY RATING DEVELOPED USING WSPVRT.

```

1SITES -----
XEQ 02/10/2011          New Creek Site 17          WSID= NC17
VER 2005.1.04          SUBW= 17
TIME 16:22:53          SITE = 17          PASS= 1          PART= 2
  
```

```

PERM POOL          1104.12 FT          25.5 ACFT          0.00 AC          0.0 CFS
  
```



## New Creek Site 17 – ASW Integrity (6-hr)

RATING TABLE NUMBER 2

	ELEV. FEET	Q-TOTAL CFS	Q-PS CFS	Q-AUX. CFS	VOLUME AC-FT	AREA ACRE
1	1104.12	0.00	0.00	0.00	25.46	0.00
2	1104.35	0.40	0.40	0.00	26.19	0.00
3	1104.58	1.13	1.13	0.00	26.91	0.00
TRANSITION TO ORIFICE FLOW, ELEV = 1104.81 FT						
4	1104.81	2.08	2.08	0.00	27.64	0.00
5	1112.67	18.91	18.91	0.00	72.04	0.00
6	1120.54	26.65	26.65	0.00	142.39	0.00
7	1128.40	32.61	32.61	0.00	245.87	0.00
8	1128.79	41.96	41.96	0.00	251.64	0.00
9	1129.18	58.83	58.83	0.00	257.41	0.00
FULL CONDUIT FLOW, ELEV = 1129.57 FT						
10	1129.57	80.60	80.60	0.00	263.18	0.00
11	1131.75	82.27	82.27	0.00	301.26	0.00
12	1133.92	83.86	83.86	0.00	340.80	0.00
13	1136.10	85.42	85.42	0.00	384.50	0.00
14	1137.29	724.25	86.27	637.98	410.72	0.00
15	1138.49	2055.79	87.11	1968.69	436.96	0.00
16	1140.64	5747.69	88.59	5659.10	487.12	0.00
17	1143.27	11884.28	90.38	11793.90	556.92	0.00
18	1148.05	27678.50	93.53	27584.97	703.94	0.00
19	1154.03	53064.41	97.33	52967.07	901.97	0.00
20	1160.00	85264.31	100.99	85163.32	1100.00	0.00

\*\*\*\*\*

SUMMARY OF AUXILIARY SPILLWAY SURFACE CONDITIONS USED IN COMPUTATIONS BY REACH

REACH	FROM STA (ft)	TO STA (ft)	SLOPE (%)	RETARDANCE CURVE INDEX@	VEGETAL COVER FACTOR	MAINT. CODE +	ROOTING DEPTH (ft)	REACH LOCATION *
1	0.	25.	-20.0	0.020	**	**	**	INLET
2	25.	63.	-2.9	0.035	**	**	**	INLET
3	63.	83.	0.0	0.035	**	**	**	CREST
4	83.	139.	2.0	0.035	0.50	1	1.0	EXIT !
5	139.	207.	7.4	0.035	0.50	1	1.0	exit
6	207.	314.	9.3	0.035	0.50	1	1.0	exit
7	314.	445.	3.8	0.035	0.50	1	1.0	exit
8	445.	539.	5.3	0.035	0.50	1	1.0	exit
9	539.	626.	5.7	0.035	0.50	1	1.0	exit
10	626.	668.	11.9	0.035	0.50	1	1.0	exit
11	668.	792.	12.1	0.035	0.50	1	1.0	exit
12	792.	835.	11.6	0.035	0.50	1	1.0	exit
13	835.	869.	17.9	0.035	0.50	1	1.0	exit

@ The program interprets retardance curve index entries of less than 1 as Manning's n values.

+ The minimum maintenance code value of 2 is used in INTEGRITY computations (the program changes values of 1 to 2 during computation).

\* Upper case indicates a reach of constructed spillway channel.

\*\* The program does not use vegetal cover factor, maintenance code, and rooting depth for inlet and crest reaches in computations.

! Reach 4 used in computing exit channel velocities.

\*\*\*\*\*

ROUTED RESULTS	BTM WIDTH FT	MAX ELEV FT	VOL-MAX ACFT	AREA-MAX AC	AUX.-HP FT	VOL-AUX. ACFT
NRCS-SDH	200.0	1137.59	417.1	0.0	1.49	32.6
	PEAK - CFS DISCHARGE =	Q-PS 86.	Q-AUX. 963.	Q-TOT. 1049.		
		CRITICAL DEPTH FT	CRITICAL VELOCITY FT/SEC	CRITICAL SLOPE-Sc FT/FT	25% OF Q Sc FT/FT	
	AUXILIARY SPILLWAY ---	0.89	5.33	0.019	0.025	

## New Creek Site 17 – ASW Integrity (6-hr)

AUXILIARY SPILLWAY DURATION FLOW = 4.0 HOURS

EXIT CHANNEL FLOW SUPERCRITICAL: MAX VELOCITY= 5.4 FT/SEC  
 EXIT SLOPE = 0.020 FT/FT  
 FLOW DEPTH = 0.9 FT

\*\*\*\*\*

EROSIONALLY EFFECTIVE STRESS FOR STABILITY ANALYSIS OF AUX. EXIT CHANNEL  
 (Refer to Ag. Handbook 667, Chapt. 3, for allowable stresses.)

Aux. Spillway Discharge = 963. cfs; Bottom Width = 200. ft

REACH NO.	FROM STA	TO STA	SLOPE %	MANNING`S n	VELOCITY ft/s	TOTAL STRESS lb/ft^2	EFFECTIVE STRESS lb/ft^2
4	83.	139.	1.96	0.035	5.42	1.08	0.134

\*\*\*\*\*

ROUTED RESULTS	BTM WIDTH FT	MAX ELEV FT	VOL-MAX ACFT	AREA-MAX AC	AUX.-HP FT	VOL-AUX. ACFT
NRCS-FBH	200.0	1143.88	573.1	0.0	7.78	188.6

PEAK - CFS DISCHARGE = Q-PS 91. Q-AUX. 13533. Q-TOT. 13623.

	CRITICAL DEPTH FT	CRITICAL VELOCITY FT/SEC	CRITICAL SLOPE-Sc FT/FT	25% OF Q Sc FT/FT
AUXILIARY SPILLWAY ---	5.11	12.45	0.011	0.014

INTEGRITY ANALYSIS - REACH SURFACE PERFORMANCE SUMMARY

(The auxiliary spillway began flow at time = 2.5 hours and peaked at time = 3.0 hours.)

REACH 4: FROM STATION 83. TO 139. ON 2.0% SLOPE.  
 Surface unfailed: Stressed to 71% of allowable.

REACH 5: FROM STATION 139. TO 207. ON 7.4% SLOPE.  
 Vegetal cover failed and concentrated flow developed at time = 2.9 hours.

REACH 6: FROM STATION 207. TO 314. ON 9.3% SLOPE.  
 Vegetal cover failed and concentrated flow developed at time = 2.8 hours.

REACH 7: FROM STATION 314. TO 445. ON 3.8% SLOPE.  
 Vegetal cover failed and concentrated flow developed at time = 2.8 hours.

REACH 8: FROM STATION 445. TO 539. ON 5.3% SLOPE.  
 Vegetal cover failed and concentrated flow developed at time = 5.1 hours.

REACH 9: FROM STATION 539. TO 626. ON 5.7% SLOPE.  
 Vegetal cover failed and concentrated flow developed at time = 4.9 hours.

REACH 10: FROM STATION 626. TO 668. ON 11.9% SLOPE.  
 Vegetal cover failed and concentrated flow developed at time = 2.7 hours.

REACH 11: FROM STATION 668. TO 792. ON 12.1% SLOPE.  
 Vegetal cover failed and concentrated flow developed

# New Creek Site 17 – ASW Integrity (6-hr)

at time = 2.7 hours.

REACH 12: FROM STATION 792. TO 835. ON 11.6% SLOPE.  
 Vegetal cover failed and concentrated flow developed  
 at time = 2.7 hours.

REACH 13: FROM STATION 835. TO 869. ON 17.9% SLOPE.  
 Vegetal cover failed and concentrated flow developed  
 at time = 2.7 hours.

INTEGRITY ANALYSIS - HEADCUT EROSION DAMAGE SUMMARY

The most upstream headcut began at station 139.  
 and progressed upstream to station 139.  
 The final height of the headcut was 2.2 ft.

The headcut having the maximum final overfall height began  
 at station 835. and progressed upstream to station 834.  
 The final height of the headcut was 3.9 ft.

	DURATION FLOW HRS	ATTACK OE/B ACFT/FT	DIST. FROM MOST U/S HEADCUT TO U/S EDGE AUX. CREST, FT
AUXILIARY SPILLWAY ---	5.7	8.5	76.

EXIT CHANNEL FLOW SUPERCRITICAL: MAX VELOCITY= 15.1 FT/SEC  
 EXIT SLOPE = 0.020 FT/FT  
 FLOW DEPTH = 4.3 FT

Inflow Hyd 1 SDH-Peak = 1049.20 CFS at 4.58 hrs., Location Point  
 Inflow Hyd 1 FBH-Peak = 13623.41 CFS at 2.96 hrs., Location Point  
 HYDOUT 1 17

1SITES....JOB NO. 1 COMPLETE.

-----  
 NC17 New Creek Site 17  
 0 SUBWATERSHED(S) ANALYZED.  
 1 STRUCTURE(S) ANALYZED.  
 2 HYDROGRAPHS ROUTED AT LOWEST SITE.  
 0 TRIALS TO OBTAIN BOTTOM WIDTH FOR SPECIFIED STRESS OR VELOCITY.  
 \*\*\*\*\*

SITES....COMPUTATIONS COMPLETE

1 SUMMARY TABLE 1 SITES VERSION 2005.1.04  
 ----- DATED 01/01/2005

WATERSHED ID	RUN DATE		RUN TIME						
-----	-----	-----	-----	-----					
NC17	02/10/2011		16:22:53						
>>>	SITE ID	SUBWS ID	SUBWS DA (SQ MI)	CURVE NO.	TC (HRS)	TOTAL DA (SQ MI)	TYPE DESIGN	STRUC CLASS	<<<
	-----	-----	-----	-----	-----	-----	-----	-----	-----
	17	17	1.70	72.	0.78	1.70	TR60	C	

## New Creek Site 17 – ASW Integrity (6-hr)

PASS NO.	DIA./ WIDTH (IN/FT)	AUX.CREST ELEV (FT)	BTM. WIDTH (FT)	MAX. HP (FT)	MAX. ELEV (FT)	EMB. VOL. (CY)	INTEGR.* DIST. (FT)	EXIT* VEL. (FT/SEC)	TYPE HYD
1	24.0	1136.1	200.0	7.8	1143.9	0.	76.	15.1	NRCS-FBH

\* INTEGRITY DIST. AND EXIT VEL. VALUES ARE BASED ON THE ROUTED HYDROGRAPH SHOWN UNDER TYPE HYD.

SITES.....SUMMARY TABLE 1 COMPLETED.

NRCS SITES VERSION 2005.1.04 ,01/01/2005  
NC17 FILES

INPUT = W:\426\Active Jobs\52299 - WV NRCS 2010 Contract\05 Working\41 Dam Assessments\New Creek Site 17\NC17 SITES Model\NC17\NC\_Site17\_ASW\_6Hr\_Integrity.D2C  
OUTPUT = W:\426\Active Jobs\52299 - WV NRCS 2010 Contract\05 Working\41 Dam Assessments\New Creek Site 17\NC17 SITES Model\NC17\NC\_Site17\_ASW\_6Hr\_Integrity.OUT  
DATED 02/10/2011 16:22:53

### GRAPHICS FILES GENERATED

OPTION "L" = W:\426\Active Jobs\52299 - WV NRCS 2010 Contract\05 Working\41 Dam Assessments\New Creek Site 17\NC17 SITES Model\NC17\NC\_Site17\_ASW\_6Hr\_Integrity.DRG DATED 02/10/2011 16:22:53

OPTION "P" = W:\426\Active Jobs\52299 - WV NRCS 2010 Contract\05 Working\41 Dam Assessments\New Creek Site 17\NC17 SITES Model\NC17\NC\_Site17\_ASW\_6Hr\_Integrity.DHY DATED 02/10/2011 16:22:53

OPTION "E" = W:\426\Active Jobs\52299 - WV NRCS 2010 Contract\05 Working\41 Dam Assessments\New Creek Site 17\NC17 SITES Model\NC17\NC\_Site17\_ASW\_6Hr\_Integrity.DEM DATED 02/10/2011 16:22:53

AUX.GRAPHICS = W:\426\Active Jobs\52299 - WV NRCS 2010 Contract\05 Working\41 Dam Assessments\New Creek Site 17\NC17 SITES Model\NC17\NC\_Site17\_ASW\_6Hr\_Integrity.DG\* DATED 02/10/2011 16:22:53



---

## SITES Output

New Creek Site 17 - ASW Integrity (24-hr)

---

# New Creek Site 17 – ASW Integrity (24-hr)

```

1*****
SITES XEQ 02/10/2011  WATER RESOURCE SITE ANALYSIS COMPUTER PROGRAM
VER 2005.1.04          (USER MANUAL - DATED DECEMBER 2005)
TIME 16:23:22
  
```

\*\*\*\*\* 80-80 LIST OF INPUT DATA \*\*\*\*\*

```

SITES      01/01/2005NC17      New Creek Site 17      1.696875  C2
SAVMOV     0      101
SAVMOV     101  1
STRUCTURE  17
  
```

```

          1090      0
          1095      3.4
          1100      12.4
          1105      28.25
          1110      53.1
          1115      88.55
          1120      136
          1125      195.65
          1130      269.5
          1135      360.35
          1140      470.1
          1145      602.85
          1160      1100
  
```

ENDTABLE

```

WSDATA     2C 17  AC 72      1086      0.78
BASEFLOW   0.95
RAINTABLE  17      24
          0      0.008      0.0162      0.0246      0.0333
          0.0425      0.0524      0.063      0.0743      0.0863
          0.099      0.1124      0.1265      0.142      0.1595
          0.18      0.205      0.255      0.345      0.437
          0.53      0.603      0.633      0.66      0.684
          0.705      0.724      0.742      0.759      0.775
          0.79      0.8043      0.818      0.8312      0.8439
          0.8561      0.8678      0.879      0.8898      0.9002
          0.9103      0.9201      0.9297      0.9391      0.9483
          0.9573      0.9661      0.9747      0.9832      0.9916
          1
  
```

ENDTABLE

```

PDIRECT
POOLDATA   ELEV      1104.12      1104.12      1104.12      1086      1074      TC
PSINLET    ELEV      0.75      12      1128.40      1.18      1.18
PSDATA     1      280.33      24      0.013      1076.01
ASSURFACE  41      139      0.1
          0      25      0.02      0.5      1      1
          25      139      0.035      0.5      1      1
          139      891      0.035      0.5      1      1
  
```

ENDTABLE

```

ASDATA     41      2.5      1
BTMWIDTH   FEET      200
ASMATERIAL
          1      12      0.004      28      125      0.37
          2      0      0.5      0      110      2
  
```

ENDTABLE

```

ASCOORD     1      Soil      Y
          0      1130      25      1135      63      1136.1
          83      1136.1      139      1135      207      1130
          314.00      1120      444.60      1115      539.00      1110
          626.00      1105      668.00      1100      792.00      1085
          835.00      1080      891.00      1070
  
```

ENDTABLE

```

ASCOORD     2      Shale
          0      1125      139      1125      207      1120
          314      1100      626      1085      891      1060
  
```

ENDTABLE

GRAPHICS I

# New Creek Site 17 – ASW Integrity (24-hr)

```
GO,DESIGN L          17          24          1104.12
SAVMOV   2    101   1          17
ENDJOB
```

\*\*\*\*\*

\*\*\*\*\* MESSAGE - DRAINAGE AREA FROM WSDATA CONTROL BEING CONVERTED FROM ACRES TO SQUARE MILES FOR COMPUTATION PURPOSES.

\*\*\*\*\* MESSAGE - DEFAULT TOPSOIL FILL MATERIAL PARAMETERS USED.

\*\*\*\*\* WARNING - HEADCUT ERODIBILITY INDEX OF 2.0 (MATERIAL 2) APPEARS INCONSISTENT WITH DENSITY OF 110.0.

\*\*\*\*\* MESSAGE - AUXILIARY SPILLWAY CREST ELEVATION IS SET TO 1136.10 FROM THE ASCOORD RECORDS.

```
1SITES -----
XEQ 02/10/2011          New Creek Site 17          WSID= NC17
VER 2005.1.04          SUBW= 17
TIME 16:23:22          SITE = 17          PASS= 1          PART= 1
```

```
***** MATERIAL PROPERTIES *****
          DRY          PERCENT          DETACH.          REP.
MATERIAL          PI          DENSITY          Kh          CLAY          RATE          DIAMETER
          lbs/CuFt          (Ft/H)/(lb/SqFt)          inches
Soil          12.          125.          0.37          28.0          --          0.00400
Shale          0.          110.          2.00          0.0          --          0.50000
TS_FILL          0.          100.          0.05          0.0          --          0.05000
GEN_FILL          12.          125.          0.37          28.0          --          0.00400
```

```
***** BASIC DATA *****
HUMID- SUBHUMID CLIMATE AREA          DESIGN CLASS C
```

STORM DISTRIBUTION AUX. -

```
PRECIP. - Q-PS,1-DAY          Q-PS,10-DAY          P-SD          P-FB
          0.00          0.00          13.40          34.80

WSDATA - CN          DA-SM          TC/L          -/H          QRF
          72.00          1.70          0.78          0.00          0.00

SITEDATA- PERM POOL          CREST PS          FP SED          VALLEY FL          378?
          1104.12          1104.12          1104.12          1074.00          NO

          BASEFLOW          INITIAL EL          EXTRA VOL          SITE TYPE
          0.95          0.00          0.00          DESIGN

PSDATA - NO. COND          COND L          DIA/W          -/H
          1.00          280.33          24.00          0.00

          PS N          KE          WEIR L          TW EL
          0.013          0.75          12.00          1076.01

          2ND STG          ORF H          ORF L          START AUX.
          1128.40          1.18          1.18          1104.12

ASCRESTS - AUX.1          AUX.2          AUX.3          AUX.4          AUX.5
          1136.10          0.00          0.00          0.00          0.00

AUX.DATA - REF.NO.          RETARD. Ci          TIE STATION          INLET LENGTH
          41          0.00          83.00          0

AUX.DATA - INLET N          SIDE SLOPE          EXIT N          EXIT SLOPE          ACTUAL AUX?
          0.035          2.50          0.035          0.020          YES

BTM WIDTH - BW1          BW2          BW3          BW4          BW5
```



# New Creek Site 17 – ASW Integrity (24-hr)

NRCS-FBH      D= 24.00 HR      P= 34.80 IN      Q= 30.53 IN      DA= 1.70 SM  
 TC= 0.78 HR      CN= 72.00      VOL= 2766.5 ACFT

PEAK = 6917.3 CFS, AT 9.7 HRS.

\*\*\*\*\*  
 RATING TABLE DEVELOPED, SITE = 17 :  
 BY PROGRAM FOR PS AND AUX. SPILLWAYS  
 AUX. RATING USED WSPVRT METHOD.

RATING TABLE NUMBER 2

	ELEV. FEET	Q-TOTAL CFS	Q-PS CFS	Q-AUX. CFS	VOLUME AC-FT	AREA ACRE
1	1104.12	0.00	0.00	0.00	25.46	0.00
2	1104.35	0.40	0.40	0.00	26.19	0.00
3	1104.58	1.13	1.13	0.00	26.91	0.00
TRANSITION TO ORIFICE FLOW, ELEV = 1104.81 FT						
4	1104.81	2.08	2.08	0.00	27.64	0.00
5	1112.67	18.91	18.91	0.00	72.04	0.00
6	1120.54	26.65	26.65	0.00	142.39	0.00
7	1128.40	32.61	32.61	0.00	245.87	0.00
8	1128.79	41.96	41.96	0.00	251.64	0.00
9	1129.18	58.83	58.83	0.00	257.41	0.00
FULL CONDUIT FLOW, ELEV = 1129.57 FT						
10	1129.57	80.60	80.60	0.00	263.18	0.00
11	1131.75	82.27	82.27	0.00	301.26	0.00
12	1133.92	83.86	83.86	0.00	340.80	0.00
13	1136.10	85.42	85.42	0.00	384.50	0.00
14	1137.29	724.25	86.27	637.98	410.72	0.00
15	1138.49	2055.79	87.11	1968.69	436.96	0.00
16	1140.64	5747.69	88.59	5659.10	487.12	0.00
17	1143.27	11884.28	90.38	11793.90	556.92	0.00
18	1148.05	27678.50	93.53	27584.97	703.94	0.00
19	1154.03	53064.41	97.33	52967.07	901.97	0.00
20	1160.00	85264.31	100.99	85163.32	1100.00	0.00

\*\*\*\*\*

SUMMARY OF AUXILIARY SPILLWAY SURFACE CONDITIONS USED IN COMPUTATIONS BY REACH

REACH	FROM STA (ft)	TO STA (ft)	SLOPE (%)	RETARDANCE CURVE INDEX@	VEGETAL COVER FACTOR	MAINT. CODE +	ROOTING DEPTH (ft)	REACH LOCATION *
1	0.	25.	-20.0	0.020	**	**	**	INLET
2	25.	63.	-2.9	0.035	**	**	**	INLET
3	63.	83.	0.0	0.035	**	**	**	CREST
4	83.	139.	2.0	0.035	0.50	1	1.0	EXIT !
5	139.	207.	7.4	0.035	0.50	1	1.0	exit
6	207.	314.	9.3	0.035	0.50	1	1.0	exit
7	314.	445.	3.8	0.035	0.50	1	1.0	exit
8	445.	539.	5.3	0.035	0.50	1	1.0	exit
9	539.	626.	5.7	0.035	0.50	1	1.0	exit
10	626.	668.	11.9	0.035	0.50	1	1.0	exit
11	668.	792.	12.1	0.035	0.50	1	1.0	exit
12	792.	835.	11.6	0.035	0.50	1	1.0	exit
13	835.	869.	17.9	0.035	0.50	1	1.0	exit

@ The program interprets retardance curve index entries of less than 1 as Manning's n values.  
 + The minimum maintenance code value of 2 is used in INTEGRITY computations (the program changes values of 1 to 2 during computation).  
 \* Upper case indicates a reach of constructed spillway channel.  
 \*\* The program does not use vegetal cover factor, maintenance code, and rooting depth for inlet and crest reaches in computations.  
 ! Reach 4 used in computing exit channel velocities.  
 \*\*\*\*\*

## New Creek Site 17 – ASW Integrity (24-hr)

ROUTED RESULTS	BTM WIDTH	MAX ELEV	VOL-MAX	AREA-MAX	AUX.-HP	VOL-AUX.
NRCS-SDH	FT	FT	ACFT	AC	FT	ACFT
	200.0	1137.64	418.3	0.0	1.54	33.8

PEAK - CFS                      Q-PS                      Q-AUX.                      Q-TOT.  
DISCHARGE =                      87.                      1024.                      1111.

	CRITICAL	CRITICAL	CRITICAL	25% OF Q
	DEPTH	VELOCITY	SLOPE-Sc	Sc
AUXILIARY	FT	FT/SEC	FT/FT	FT/FT
SPILLWAY ---	0.93	5.44	0.018	0.025

AUXILIARY SPILLWAY DURATION FLOW =                      14.9 HOURS

EXIT CHANNEL FLOW SUPERCRITICAL: MAX VELOCITY=    5.5 FT/SEC  
EXIT SLOPE = 0.020 FT/FT  
FLOW DEPTH = 0.9 FT

\*\*\*\*\*

EROSIONALLY EFFECTIVE STRESS FOR STABILITY ANALYSIS OF AUX. EXIT CHANNEL  
(Refer to Ag. Handbook 667, Chapt. 3, for allowable stresses.)

Aux. Spillway Discharge = 1024. cfs; Bottom Width = 200. ft

REACH NO.	FROM STA	TO STA	SLOPE %	MANNING'S n	VELOCITY ft/s	TOTAL STRESS lb/ft^2	EFFECTIVE STRESS lb/ft^2
4	83.	139.	1.96	0.035	5.55	1.12	0.139

\*\*\*\*\*

ROUTED RESULTS	BTM WIDTH	MAX ELEV	VOL-MAX	AREA-MAX	AUX.-HP	VOL-AUX.
NRCS-FBH	FT	FT	ACFT	AC	FT	ACFT
	200.0	1141.12	499.9	0.0	5.02	115.4

PEAK - CFS                      Q-PS                      Q-AUX.                      Q-TOT.  
DISCHARGE =                      89.                      6780.                      6869.

	CRITICAL	CRITICAL	CRITICAL	25% OF Q
	DEPTH	VELOCITY	SLOPE-Sc	Sc
AUXILIARY	FT	FT/SEC	FT/FT	FT/FT
SPILLWAY ---	3.25	10.03	0.012	0.017

INTEGRITY ANALYSIS - REACH SURFACE PERFORMANCE SUMMARY  
(The auxiliary spillway began flow at time = 8.2 hours  
and peaked at time = 9.8 hours.)

REACH 4: FROM STATION 83. TO 139. ON 2.0% SLOPE.  
Vegetal cover failed and concentrated flow developed  
at time = 18.0 hours.

REACH 5: FROM STATION 139. TO 207. ON 7.4% SLOPE.  
Vegetal cover failed and concentrated flow developed  
at time = 10.6 hours.

REACH 6: FROM STATION 207. TO 314. ON 9.3% SLOPE.  
Vegetal cover failed and concentrated flow developed  
at time = 10.3 hours.

REACH 7: FROM STATION 314. TO 445. ON 3.8% SLOPE.  
Vegetal cover failed and concentrated flow developed  
at time = 10.3 hours.

REACH 8: FROM STATION 445. TO 539. ON 5.3% SLOPE.  
Vegetal cover failed and concentrated flow developed  
at time = 11.4 hours.

## New Creek Site 17 – ASW Integrity (24-hr)

REACH 9: FROM STATION 539. TO 626. ON 5.7% SLOPE.  
 Vegetal cover failed and concentrated flow developed  
 at time = 11.1 hours.

REACH 10: FROM STATION 626. TO 668. ON 11.9% SLOPE.  
 Vegetal cover failed and concentrated flow developed  
 at time = 10.0 hours.

REACH 11: FROM STATION 668. TO 792. ON 12.1% SLOPE.  
 Vegetal cover failed and concentrated flow developed  
 at time = 10.0 hours.

REACH 12: FROM STATION 792. TO 835. ON 11.6% SLOPE.  
 Vegetal cover failed and concentrated flow developed  
 at time = 10.0 hours.

REACH 13: FROM STATION 835. TO 869. ON 17.9% SLOPE.  
 Vegetal cover failed and concentrated flow developed  
 at time = 8.9 hours.

### INTEGRITY ANALYSIS - HEADCUT EROSION DAMAGE SUMMARY

The most upstream headcut began at station 83.  
 and progressed upstream to station 83.  
 The final height of the headcut was 0.8 ft.

The headcut having the maximum final overfall height began  
 at station 835. and progressed upstream to station 834.  
 The final height of the headcut was 5.9 ft.

	DURATION	ATTACK	DIST. FROM MOST U/S
	FLOW	OE/B	HEADCUT TO U/S EDGE
AUXILIARY	HRS	ACFT/FT	AUX. CREST, FT
SPILLWAY ---	17.6	11.3	20.

EXIT CHANNEL FLOW SUPERCRITICAL: MAX VELOCITY= 11.6 FT/SEC  
 EXIT SLOPE = 0.020 FT/FT  
 FLOW DEPTH = 2.8 FT

Inflow Hyd 1 SDH-Peak = 1110.59 CFS at 10.83 hrs., Location Point  
 Inflow Hyd 1 FBH-Peak = 6869.28 CFS at 9.84 hrs., Location Point  
 HYDOUT 1 17

1SITES....JOB NO. 1 COMPLETE.

- 
- NC17            New Creek Site 17
- 0 SUBWATERSHED(S) ANALYZED.
  - 1 STRUCTURE(S) ANALYZED.
  - 2 HYDROGRAPHS ROUTED AT LOWEST SITE.
  - 0 TRIALS TO OBTAIN BOTTOM WIDTH FOR SPECIFIED STRESS OR VELOCITY.

\*\*\*\*\*

# New Creek Site 17 – ASW Integrity (24-hr)

SITES.....COMPUTATIONS COMPLETE

1 SUMMARY TABLE 1 SITES VERSION 2005.1.04  
 ----- DATED 01/01/2005

WATERSHED ID		RUN DATE					RUN TIME		
-----		-----					-----		
NC17		02/10/2011					16:23:22		
>>>	SITE ID	SUBWS ID	SUBWS DA (SQ MI)	CURVE NO.	TC (HRS)	TOTAL DA (SQ MI)	TYPE DESIGN	STRUC CLASS	<<<
	-----	-----	-----	-----	-----	-----	-----	-----	
	17	17	1.70	72.	0.78	1.70	TR60	C	
PASS NO.	DIA./ WIDTH (IN/FT)	AUX.CREST ELEV (FT)	BTM. WIDTH (FT)	MAX. HP (FT)	MAX. ELEV (FT)	EMB. VOL. (CY)	INTEGR.* DIST. (FT)	EXIT* VEL. (FT/SEC)	TYPE HYD
-----	-----	-----	-----	-----	-----	-----	-----	-----	-----
1	24.0	1136.1	200.0	5.0	1141.1	0.	20.	11.6	NRCS-FBH

\* INTEGRITY DIST. AND EXIT VEL. VALUES ARE BASED ON THE ROUTED HYDROGRAPH SHOWN UNDER TYPE HYD.

SITES.....SUMMARY TABLE 1 COMPLETED.

NRCS SITES VERSION 2005.1.04 ,01/01/2005  
 NC17 FILES

INPUT = W:\426\Active Jobs\52299 - WV NRCS 2010 Contract\05 Working\41 Dam Assessments\New Creek Site 17\NC17 SITES Model\NC17\NC\_Sitel7\_ASW\_24Hr\_Integrity.D2C  
 OUTPUT = W:\426\Active Jobs\52299 - WV NRCS 2010 Contract\05 Working\41 Dam Assessments\New Creek Site 17\NC17 SITES Model\NC17\NC\_Sitel7\_ASW\_24Hr\_Integrity.OUT  
 DATED 02/10/2011 16:23:22

GRAPHICS FILES GENERATED

OPTION "L" = W:\426\Active Jobs\52299 - WV NRCS 2010 Contract\05 Working\41 Dam Assessments\New Creek Site 17\NC17 SITES Model\NC17\NC\_Sitel7\_ASW\_24Hr\_Integrity.DRG  
 DATED 02/10/2011 16:23:22

OPTION "P" = W:\426\Active Jobs\52299 - WV NRCS 2010 Contract\05 Working\41 Dam Assessments\New Creek Site 17\NC17 SITES Model\NC17\NC\_Sitel7\_ASW\_24Hr\_Integrity.DHY  
 DATED 02/10/2011 16:23:22

OPTION "E" = W:\426\Active Jobs\52299 - WV NRCS 2010 Contract\05 Working\41 Dam Assessments\New Creek Site 17\NC17 SITES Model\NC17\NC\_Sitel7\_ASW\_24Hr\_Integrity.DEM  
 DATED 02/10/2011 16:23:22

AUX.GRAPHICS = W:\426\Active Jobs\52299 - WV NRCS 2010 Contract\05 Working\41 Dam Assessments\New Creek Site 17\NC17 SITES Model\NC17\NC\_Sitel7\_ASW\_24Hr\_Integrity.DG\*  
 DATED 02/10/2011 16:23:22



---

Appendix D  
Evaluation of Potential Rehabilitation  
Projects-Priority Ranking Spreadsheet

---

**EVALUATION OF POTENTIAL REHABILITATION PROJECTS**

<b>STATE</b>	WV	<b>DAM</b>	New Creek Site 17		<b>BY</b>	TAR	<b>DATE</b>	02/17/11	
<b>YEAR BUILT</b>		1960	<b>DESIGN HAZARD CLASS</b>		C	<b>DRAINAGE AREA</b>		1.7	mi2
<b>WORK PLAN DATE</b>		1956	<b>CURRENT HAZARD CLASS</b>		C	<b>DAM HEIGHT</b>		68.29	ft

sht 1 of 5 CONSEQUENCES OF DAM FAILURE ver 100101

**POTENTIAL DAM FAILURE:**

Total Failure Index 273 A

**POTENTIAL LOSS OF LIFE:**

Maximum Population-at-Risk [PAR] (number) 1143 B

Total Risk Index 12482 C

**POTENTIAL LOSS OF PROPERTY:**

Identify major community affected by breach and rate impact as High (H), Medium (M), Low (L) or None(blank)

Community Claysville (H,M,L,-) H D

Number of homes, businesses, major buildings (number) 457 E

**POTENTIAL LIFELINE DISRUPTION:**

Water supply, identify community disrupted by dam failure, and estimate number/amount

Municipal sole source \_\_\_\_\_ Users (number)  F

Supplemental source \_\_\_\_\_ Users (number)  G

Irrigation water \_\_\_\_\_ Storage (Ac-Ft)  H

**POTENTIAL INFRASTRUCTURE DISRUPTION:**

Transportation system crossings, identify major crossing rendered unusable by dam failure, and estimate number

Major/Interstate U.S. Routes 50 and 220 Roads (number) 2 I

Secondary/County WV Rte 972, Co Rtes 220/3,220/6,220/2,220/5,220/1, Roads (number) 7 J

**POTENTIAL ADVERSE IMPACTS ON THE ENVIRONMENT:**

Describe impacts and rate each as High (H), Medium (M), Low (L), or None (blank)

Threatened & endangered species \_\_\_\_\_ (H,M,L,-) L K

Sensitive riparian areas \_\_\_\_\_ (H,M,L,-) L L

Contaminated reservoir sediment \_\_\_\_\_ (H,M,L,-) L M

Wetland and wildlife habitat \_\_\_\_\_ (H,M,L,-) L N

Other \_\_\_\_\_ (H,M,L,-)  O

**POTENTIAL ADVERSE SOCIAL IMPACTS:**

Describe impacts and rate each as High (H), Medium (M), Low (L) or None(blank)

Known cultural resources \_\_\_\_\_ (H,M,L,-) L P

Historic preservation issues \_\_\_\_\_ (H,M,L,-)  Q

Socially disadvantaged community \_\_\_\_\_ (H,M,L,-) M R

**POTENTIAL ADVERSE ECONOMIC IMPACTS:**

Average annual benefits attributed to this dam, updated workplan value ( \$ ) 56,088 S

Changes in benefits since workplan; Increase(I), No change(NC), Decrease(D) (I,NC,D) I T

Low income families impacted (number) 208 U

**INPUT BY STATE DAM SAFETY AGENCY:**

State dam safety order issued for repair, modification, removal issued, Yes(Y), No(N) ( Y,N )  V

State Dam Safety Agency Priority, High(H), Medium(M), Low(L), None(blank) (H,M,L,-)  W

**OTHER CONSIDERATIONS:**

Identify any other considerations and rate as High(H), Medium(M), Low(L) or None(blank)

\_\_\_\_\_ (H,M,L,-)  X

\_\_\_\_\_ (H,M,L,-)  Y

**EVALUATION OF POTENTIAL REHABILITATION PROJECTS**

<b>STATE</b>	<b>WV</b>	<b>DAM</b>	New Creek Site 17	<b>BY</b>	TAR	<b>DATE</b>	02/17/11	
sht 2 of 5		<b>FAILURE &amp; RISK INDEXES</b>					ver 102201	

Adopted from Bureau of Reclamation "Risk Based Profile System"

see: <http://www.usbr.gov/dsis/risk/rbpsdocumentation.pdf>

**LIFE LOSS:**

Population-at-Risk [PAR], see NRCS dams inventory definition (number of people)

Estimate PAR for static loading failure, typically assume water at top of dam	1143	A
Estimate PAR for hydrologic loading failure, typically assume water at top of dam	1143	B
Estimate PAR for seismic loading failure, typically assume water at ES crest (sunny day failure)	1143	C

Fatality Rates [FR] from dam breach

Adopted from BuRec "A Procedure for Estimating Loss of Life Caused by Dam Failure" DSO-99-06

see: [http://www.usbr.gov/research/dam\\_safety/documents/dso-99-06.pdf](http://www.usbr.gov/research/dam_safety/documents/dso-99-06.pdf)

Flood Severity/Lethality [DV] is the average depth [D] times velocity [V] across flood plain (ft2/sec)

$$DV = (\text{breach discharge} - \text{bank full discharge}) / \text{breach floodplain width}$$

Warning Time [T] between failure warning and flood wave at population (minutes)

Flood Severity Understanding [U] of the warning issuer of the likely flooding magnitude

scenario	breach discharge	bankfull discharge	breach width	DV	warning time	under-standing
	(cfs)	(cfs)	(ft)	(ft2/sec)	(minutes)	(N/A or Vague)
Static	59590	89	659	90	3	Vague
Hydrologic	100293	89	708	142	2	Vague
Seismic	59590	89	659	90	3	Vague

For DV>50	T=0	U=N/A (no warning)	FR=0.15
For DV>50	T<60	U=vague	FR=0.04
For DV>50	T>60	U=vague	FR=0.03
For DV<50	T=0	U=N/A (no warning)	FR=0.01
For DV<50	T<60	U=vague	FR=0.007
For DV<50	T>60	U=vague	FR=0.0003

Estimate FR for static loading failure scenario	0.04	D
Estimate FR for hydrologic loading failure scenario	0.04	E
Estimate FR for seismic loading failure scenario	0.04	F

Scenario	Load Factor	Response Factor	Failure Index	Fatality Rate	PAR	Risk Index
Static	1	116	116	0.04	1143	5304
Hydrologic	*	*	157	0.04	1143	7178
Seismic	0.00	#DIV/0!	0	0.04	1143	0
<b>TOTAL=</b>			<b>273</b>	<b>TOTAL=</b>		<b>12482</b>

EVALUATION OF POTENTIAL REHABILITATION PROJECTS								
STATE	WV	DAM	New Creek Site 17	BY	TAR	DATE	02/17/11	
sht 3 of 5		<b>STATIC FAILURE INDEX</b>					ver 100101	
<b>PRINCIPAL SPILLWAY SYSTEM</b> (60 points max):						(total points)	30	A
Downstream filter or filter zone around conduit (yes=0 or no=10)							0	B
Conduit trench deep (>2d) and narrow (<3d) and steep sideslope (<2:1) (no=0 or yes=10)							0	C
Principal spillway system (inlet, pipe, or outlet) in deteriorated condition (no=0 or yes=10)							10	D
Conduit has seepage cutoff collars or other compaction adverse features (no=0 or yes=10)							10	E
Conduit contains open joints, open cracks, steady seepage (no=0 or yes=10)							10	F
Conduit founded on competent bedrock (yes=0 or no=10)							0	G
Reservoir control gate located at outlet of conduit (no=0 or yes=10)							0	H
<b>RESERVOIR FILLING HISTORY</b> (75 points max):						(total points)	50	I
Reservoir has filled to x% of effective height (earth spillway crest minus original streambed)							73	J
(<50%=75 or 51-75%=50 or 76-90%=25 or 91-95%=10 or 96-100%=5 or >100%=0)							50	K
<b>SEEPAGE AND DEFORMATION</b> (85 points max):						(total points)		L
Seepage carrying fines, or seepage increases with reservoir elevation increases, or sinkholes/jugholes exist in embankment (no=0 or yes=80)							0	M
Large amounts of seepage (no=0 or yes=6)							0	N
Visible and significant slope movement or sloughing (no=0 or yes=6)							0	O
Longitudinal or transverse embankment cracking greater than one foot in depth (no=0 or yes=6)							0	P
Sinkholes/depressions within two times effective height of the dam, either face (no=0 or yes=6)							0	Q
Poor top of dam condition, eroded, trees, rodent holes, settlement (no=0 or yes=6)							0	R
Abnormally wet areas at downstream toe/groin of embankment (no=0 or yes=6)							0	S
Inadequate slope protection against erosion by rainfall or waves (no=0 or yes=6)							0	T
<b>FOUNDATION GEOLOGY</b> (41 points max):						(total points)	30	U
Highly fractures rock under core (no=0 or treated=3 or untreated=30)							30	V
Karst terrain and soluble rock (gypsum or limestone) (no=0 or treated=3 or untreated=30)							0	W
Collapsible soils (no=0 or treated=3 or untreated=30)							0	X
Significant stress relief fractures in abutments (no=0 or treated=3 or untreated=30)							0	Y
History of underground mining under embankment area (no=0 or treated=3 or untreated=30)							0	Z
Coarse grained and highly permeable soils (no=0 or yes=3)							0	AA
Presence of weak layers/conditions diminishing embankment stability (no=0 or yes=3)							0	AB
Erodible soils (sandy/silty materials) or weakly cemented rock (no=0 or yes=3)							0	AC
Reservoir area prone to landslides that could cause overtopping (no=0 or yes=3)							0	AD
<b>EMBANKMENT DESIGN AND CONSTRUCTION</b> (24 points max):						(total points)		AE
Filters for core or foundation or incompatibility between zones (no=3 or yes=0)							0	AF
Embankment or foundation drainage system (yes=0 or no=4)							0	AG
Erodible core material (sands, silts, dispersive clays) (no=0 or yes=4)							0	AH
Incomplete or no foundation cutoff of shallow permeable layers (no=0 or yes=4)							0	AI
Poorly placed earthfill, inadequate density (no=0 or yes=4)							0	AJ
Gate features to drain reservoir (yes=0 or no=4)							0	AK
<b>EMBANKMENT MONITORING</b> (15 points max):						(total points)	6	AL
Instruments (except surficial survey points) installed at dam (yes=0 or no=3)							3	AM
Installed instruments routinely read and evaluated (yes=0 or no=3)							3	AN
Visual inspection of dam by engineer less often than yearly (no=0 or yes=3)							0	AO
Good physical/visual access to downstream groin/toe for inspection (yes=0 or no=3)							0	AP
<b>STATIC FAILURE INDEX:</b> A+I+L+U+AE+AL							116	AQ

EVALUATION OF POTENTIAL REHABILITATION PROJECTS								
STATE	WV	DAM	New Creek Site 17	BY	TAR	DATE	02/17/11	
sht 4 of 5		HYDROLOGIC FAILURE INDEX					ver 100101	
<b>HYDROLOGIC LOADING:</b>								
Total Spillway Capacity (PS&ES) for 6hr storm [Pfb], Work Plan Tbl 3 (rainfall inches)						9.88	A	
Obtained from Work Plan Tbl 3, or dams inventory data, or computer routings								
100 year, 6hr rainfall [P100] (inches)						3.8	B	
Probable Maximum Precipitation [PMP] (inches)						27.2	C	
if Pfb < P100 = 3.8 enter 40								
if Pfb = P100+0.2(PMP-P100) = 8.48 enter 25								
if Pfb = P100+0.4(PMP-P100) = 13.16 enter 15								
if Pfb = P100+0.6(PMP-P100) = 17.84 enter 7								
if Pfb = P100+0.8(PMP-P100) = 22.52 enter 3								
if Pfb = PMP = 27.2 enter 1								
Enter interpolated value						22	D	
<b>HYDROLOGIC UNCERTAINTY:</b>								
Drainage Area [DA] (square miles)						1.7	E	
DA<10 enter 1.5 ; 10<DA<20 enter 1.4 ; 20<DA<50 enter 1.3 ; DA=>50 enter 1.2						1.5	F	
<b>PIPE SPILLWAY PLUGGING:</b>								
Pipe Diameter [D] (inches)						24	G	
D<12 enter 1.1; 12<=D<24 enter 1.0; 24<=D enter 0.9						0.9	H	
Riser & trash rack type:								
Non-standardized inlet enter 1.1, Open Top riser enter 1.0; Covered or Baffle Top enter 0.9						0.9	I	
<b>EARTH SPILLWAY FLOW:</b>								
Earth spillway flow depth [Des] from top of dam to spillway crest (feet)(10' max)						10	J	
<b>DAM EROSION RESISTANCE:</b>								
Non-plastic (PI<10) fill enter 2.0 ; Plastic core enter 1.7 ; Overtopping armoring enter 0.8						2	K	
Vegetal Cover Factor [Cf], see SITES or AH667						0.7	L	
<a href="http://www.pswcrl.ars.usda.gov/ah667/ah667.htm">http://www.pswcrl.ars.usda.gov/ah667/ah667.htm</a>								
Cf <0.4 enter 1.1; Cf < 0.7 enter 1.0; Cf<1.0 enter 0.9; larger Cf enter 0.8						0.9	M	
<b>EARTH SPILLWAY EROSION RESISTANCE:</b>								
Low, can be excavated with hand tools, enter 2.0								
PI>10 and SPT blows<8, PI<10 and SPT blows>8, Kh<0.10, seismic velocity<2000fps								
Moderate, can be excavated with construction equipment, easy ripping, enter 1.2								
PI>10 and SPT blows>8, PI<10 and SPT blows>30, Kh<10, seismic velocity<7000fps								
High, very hard ripping, requires drilling and blasting, enter 0.2								
moderately hard rock, Kh>10, seismic velocity>7000fps						2	N	
Vegetal Cover Factor [Cf], see SITES or AH667						0.7	O	
Cf <0.4 enter 1.1; Cf < 0.7 enter 1.0; Cf<1.0 enter 0.9; larger Cf enter 0.8						0.9	P	
<b>HYDROLOGIC FAILURE INDEX:</b>								
dam overtopping breach: (2)(D)(F)(H)(I)(K)(M)						96	Q	
earth spillway breach: (D+5J)(F)(H)(I)(N)(P)						157	R	
larger of (2)(D)(F)(H)(I)(K)(M) or (D+5J)(F)(H)(I)(N)(P) but less than 300						157	S	

**EVALUATION OF POTENTIAL REHABILITATION PROJECTS**

<b>STATE</b>	<b>WV</b>	<b>DAM</b>	New Creek Site 17	<b>BY</b>	TAR	<b>DATE</b>	02/17/11
sht 5 of 5	<b>SEISMIC FAILURE INDEX</b>						ver 102201

**SEISMIC LOADING:**

Latitude (degrees.decimal)	<input type="text" value="39.355"/>	A
Longitude (degrees.decimal)	<input type="text" value="-79.05"/>	B
See "http://eqint.cr.usgs.gov/eq/html/lookup.shtml"		
PGA [peak ground acceleration] for 2% chance in 50 years, see NEHRP maps (%g) if PGA is less than 10% g, enter 0 if PGA is between 10% g and 19% g, enter 0.15 if PGA is between 20% g and 39% g, enter 0.30 if PGA is between 40% g and 59% g, enter 0.65 if PGA is greater than 60% g, enter 1.0	<input type="text" value="5.477"/>	C
	<input type="text" value="0"/>	D

**FOUNDATION LIQUEFACTION:**

Select only one of the following foundation conditions which best represents the site

Loose alluvium, lacustrine, loess materials (no=0 or yes=10)	<input type="text" value="0"/>	E
Bedrock, glacial till, highly clayey materials (no=0 or yes=5)	<input type="text" value="5"/>	F

**EMBANKMENT FREEBOARD FOR FOUNDATION LIQUEFACTION:**

Dam height for seismic event is the height from top of dam to downstream channel bottom (ft)	<input type="text" value="68.29"/>	G
Freeboard for seismic event is the depth from top of dam to assumed pool surface (ft)	<input type="text" value="13.8"/>	H
Freeboard percent of dam height (%) if Freeboard is less than 25% of dam height, enter 10 if Freeboard is 25% to 50% of dam height, enter 5 if Freeboard is more than 50% of dam height, enter 1	<input type="text" value="20"/>	I
	<input type="text" value="10"/>	J

**EMBANKMENT FREEBOARD FOR EMBANKMENT CRACKING:**

Freeboard is less than or equal to 15 feet (no=0 or yes=1)	<input type="text" value="1"/>	K
--	--------------------------------	---

**EMBANKMENT CRACKING:**

Embankment contains self-healing filter zones (no=4 or yes=0)	<input type="text" value="4"/>	L
---	--------------------------------	---

**SEISMIC FAILURE INDEX:**

(D) ( (E)(J) + (F)(K+1)(L+1) ) but less than 100	<input type="text" value="0"/>	M
--	--------------------------------	---



Digitally signed by Angela D. Greene, PE  
Date: 2011.03.21 10:07:57 -04'00'

**State Conservation Engineer's Signature**  
concurring with technical content of sheets 2 thru 5

**Review Comments Related to Geotechnical Factors in the  
“Evaluation of Potential Rehabilitation Projects-Priority Ranking Spreadsheet”**

<b>Failure Index</b>	<b>Line</b>	<b>Comment</b>
Static	B	As-builts show no filter diaphragm criteria is met.
Static	C	As-builts do not show PSW excavation slopes. Thick valley soils.
Static	E	As-builts show 7 anti-seep collars constructed along the PSW.
Static	G	As-builts do not show foundation below PSW conduit.
Static	M, N	No excessive seepage observed. Seepage under PSW conduit at downstream toe.
Static	O,P,Q	Irregular downstream slope observed.
Static	R	Top of dam in fair condition. Downstream slope has excessive vegetation, particularly within rockfill.
Static	S	No wet areas observed on downstream slope.
Static	T	No erosion observed.
Static	V	As-builts show cutoff trench excavated to top of rock. No grouting completed.
Static	W	No karst geology or soluble rock mapped on West Virginia Geologic Survey publications.
Static	X	No collapsible soils identified in the design reports.
Static	Y	No stress relief fractures identified in the design reports. Kittlelick thrust fault in abutment.
Static	Z	No underground mining under embankment described in the design reports.
Static	AA	As-built profile shows average soil depths are about 20 feet thick. Testing in Soils Report has an average plasticity index of 14, which indicates that the foundation contains sufficient clay to produce a low permeability.
Static	AB	No weak layers/conditions identified in the design reports.
Static	AC	No erodible soils or weakly cemented rock identified in the design reports.
Static	AD	Susceptibility of reservoir area to landslides that could overtop dam was not assessed in the design files.
Static	AF	As-builts show three zones. Calculations for the compatibility of zones were not included in the design files.
Static	AG	As-builts do not show a seepage drain system.
Static	AH	No erodible core materials identified in the design reports.
Static	AI	As-builts show cutoff trench excavated to shale.
Static	AJ	No construction quality control embankment fill test results provided.
Static	AM	Dam does not have any instrumentation.
Hydrologic	N	Minimum shale SITES parameters used.
Seismic	E,F	Liquefaction was not evaluated in the design documents reviewed.
Seismic	L	As-builts show no filter zone.